

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

		Serial No.: RJ/CHR-158	
1. Name	SECTION I: IDENTIFICATION		
Present Past Other Name (if any): 2. Location	: Hanuman Jee Ka Well : :		
LONGITUDE 75 ⁰ 41 ['] E	LATITUDE 29 ⁰ 0 ['] N		
Address	Near Nath Jee Ki Chhatri, Churu		
Approach		District: Churu PIN: 331001 Churu city. It is 23 Km away It is well connected by regular	
3. Property Type			
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Temple	Other Structures Wall Gateway Pillar Others (specify)	
Engineering structure Bridge Tunnel Other engineering structure	<u>structures</u> v	lote: This is deep cylindrical vater reservoir. It has four ninarets.	

4. Property Use

	ABANDONED / IN USE : Abandoned
Present	
Past	: Drinking water
5. Age (Source)	
PERIOD	: 19 th Century AD
YEARS	
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	
Phone	:
7. Association	
WITH EVENTS	
In History	:
In Rituals	: Water reservoir
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
Architectural	Minarets
Archaeological	

Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

 Context Urban / Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary) Urban	
	Surrounaings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Well is oriented at East/West and faces the West.
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Minarets

10. Construction Technology

11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS