

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/CHR-229 **SECTION I: IDENTIFICATION** 1. Name Present Malchandra ki Haveli **Past** Other Name (if any): 2. Location 29⁰ 0' N LONGITUDE 75° 41' E LATITUDE **Address** Shaaitan Joda, Churu Village (village code) Post: Shaaitan Joda District: Churu State: Rajasthan **PIN**: 331001 Approach The Palace is situated at Shaaitan Joda in Churu district. It is 5 km away from Churu bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures **Other Structures** Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related domical Note: lt has structures superstructure and pillars with Public square rafters. Bridge Tunnel Park or garden Graveyard Other engineering structure Baolis, Well Tank

Cave

4. Property Use	
	ABANDONED / IN USE: Abandoned
Present	
Past	:
5. Age (Source)	
	40th Continue AD
PERIOD YEARS	: 18 th Century AD
Precise date of Construction	•
Completion	•
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protecti	on
o. Ownership / Level of 1 lotecti	SINGLE /MULTIPLE :
Public: Archaeological Survey of	
India / State Archaeology	•
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	•
7. Association	
WITH EVENTS	
In History	: Haveli
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS Detroit	
Patron Architect / Engineer	•
Any other (specify)	:
,	
8. Statement of Significance	
✓ Architectural	Pillars with rafters
Archaeological	
Historical	
Religious	
Any other (specify)	

SECTION II: DESCRIPTION

9.	Physical Description and I	Decora	ative Features
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban
	Carroananigo		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H	l) :	(m / am/fact / inch)
	Number of Blocks Number of Storys	: :	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	: :	The Palace is oriented East/West and faces the West
•	Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : : : : : : : : : : : : : : : : : : :	Dome
10.	. Construction Technology	1	
11.	Structural System Building Techniques Material of Construction Condition Assessment		Indo – Persian Arcuate Bricks & Stone
	In General	Good	/ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance Brief (Attach extra sheet if		seary).
	ackening of surface.	HECE	33ai y j.
סוכ	ionering or surface.		

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS