


INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/CHR-260

	SECTION I : IDENTIFICATION		
1. Name			
Present Past Other Name (if any):	: Mori Darwaja :		
2. Location			
LONGITUDE 75° 41' E	LATITUDE 29 ⁰ 0 ['] N		
Address	Patel Chowk, Rajgarh, Churu		
	: Village (village code) Post : Rajgarh District: Churu State : Rajasthan PIN: 331023		
Approach	: The Gateway is situated at Rajgarh in Churu district. It is 60 km away from Churu. It is well connected by regular bus services.		
3. Property Type			



4. Property Use ABANDONED / IN USE : Present Gateway : Past 5 Gateway 5. Age (Source) 19th Century AD PERIOD 2 YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address 2 Phone ÷ 7. Association WITH EVENTS In History Gateway 2 In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Pointed arch \checkmark Archaeological Historical

Religious

Any other (specify)

SECTION II: DESCRIPTION

 Context Urban / Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary) Urban			
Surrounungs		Stand in Isolation Integral part of a Landscape / Street / Complex			
 Quantification Area Dimension (L x B x H) 	:	(m / cm/ feet / inch)			
Number of Blocks Number of Storys	:	01 01			
 Spatial Organization Orientation 	:	The Gateway is oriented North/South direction and faces North			
Plan Allocation of Spaces	:				
ARCHITECTURAL STYLE Ornamentation					
Exteriors Interiors	:	Alcoves			
Movable Collections Any Other (specify)	:				

Structural System	:	Indo-Persian
Building Techniques	:	Trabeate and Arcuate
Material of Construction	:	Bricks and stone

11. Condition Assessment

Good / Fair Good

Sign of Deterioration Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	· · · · · · · · · · · · · · · · · · ·
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS