

### INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

### **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: RJ/CHR-291 **SECTION I: IDENTIFICATION** 1. Name Present Sita Well Past Other Name (if any): 2. Location 290 0' N LONGITUDE 75° 41' E **LATITUDE Address** Railway Station Road, Churu Village (village code) Post: Raj Garh District: Churu State: Rajasthan **PIN**: 331023 Approach The Well is situated at Raj Garh City in Churu district. It is 3 Km away from Churu bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures **Other Structures** Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a deep cylindrical water structures reservoir with boundary wall and 2 minarets. Bridge Public square Tunnel Park or garden Other engineering structure Graveyard Baolis, Well

Tank Cave

4. Property Use	
	ABANDONED / IN USE: Abandoned
Present	
Past	•
- 401	
5. Age (Source)	
PERIOD	: 20 <sup>th</sup> Century AD
YEARS	:
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protecti	on
	SINGLE /MULTIPLE :
Public: Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	
Any other (Please specify) Name	•
Address	•
Phone	:
7. Association	
WITH EVENTS     In History	. Wall
In History In Rituals	: Well
In Building Construction	•
Any other (specify)	:
WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
✓ Architectural	Minoroto
Archaeological	Minarets
Historical	
Religious	
Any other (specify)	

# SECTION II: DESCRIPTION

9.	Physical Description and I	Decora	ative Features
Context     Urban / Rural Setting     Surroundings			* <b>Drawings</b> (Attach extra sheet if necessary) Urban
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	<b>Quantification</b> Area Dimension ( L x B x F	H) :	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	: :	The Well is oriented East/West and faces the East.
•	Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : :	Boundary wall
10.	. Construction Technology	/	
	Structural System Building Techniques Material of Construction	: : :	Hydraulic System Cylindrical water reservoir Bricks & Stones
11.	Condition Assessment		
		<b>Good</b> Good	/ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance	)	
In	Brief (Attach extra sheet if	neces	ssary):
Bla	ackening of surface.		

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

## SECTION III: REFERENCES

### 13. Reference Sources (published and unpublished textual details)

14. Photographs	
<u> </u>	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS