

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/CHR-293 **SECTION I: IDENTIFICATION** 1. Name Present Bala Well Past Other Name (if any): 2. Location 290 0' N LONGITUDE 75° 41' E **LATITUDE Address** Railway Station Road, Churu Village (village code) Post: Raj Garh District: Churu State: Rajasthan **PIN**: 331023 Approach The Well is situated at Raj Garh City in Churu district. It is 2 Km away from Churu bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures **Other Structures** Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a deep cylindrical water structures reservoir with boundary wall and four minarets. Bridge Public square Tunnel Park or garden Other engineering structure Graveyard Baolis, Well

Tank Cave

4. Property Use		
	ABANDONED / IN USE: Abandoned	
Present	:	
Past	:	
5. Age (Source)		
PERIOD	: 20 th Century AD	
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	•	
6. Ownership / Level of Protection	on	
•	SINGLE /MULTIPLE :	
Public: Archaeological Survey of	:	
India / State Archaeology	•	
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone		
7. Association		
WITH EVENTS		
In History	: Well	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
 WITH PERSONS 		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural	Minarets	
✓ Archaeological		
Historical		
Religious Any other (specify)		
Any other (specify)		

SECTION II: DESCRIPTION

9.	Physical Description and	Decora	itive Features
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban
	ourroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x F	Н) :	(m / am/fact / inch)
	Number of Blocks Number of Storys	: :	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Well is oriented East/West and faces the East.
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : : : :	Boundary wall
10.	Construction Technology	y	
	Structural System Building Techniques Material of Construction	: : :	Hydraulic System Cylindrical water reservoir Bricks & Stones
11.	Condition Assessment		
	In General	Good Good	/ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance	Э	
In l	Brief (Attach extra sheet i	f neces	ssary):
Bla	ckening of surface.		

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
<u> </u>	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS