

## Documentation format for Archaeological / Heritage Sites / Monuments

### Serial No: RJ/CRG-043

SECTION I : IDENTIFICATION 1. Name		
Present Past Other Name (if any):	: Badi Talab :	
2. Location		
LONGITUDE 74° 54' E Address	LATITUDE 24°32' N Badi Talab, Gangrar	
	: Village (village code) Post: Gangrar State: Rajasthan	Gangrar District: Chittaurgarh PIN: 312901
Approach 3. Property Type		at Gangrar in Chittaurgarh. It aurgarh bus stand. It is well bus services.
<u>·</u> <u>·</u> ·	Deliniana atmostures	Other Structures
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel	structures	<b>Note:</b> It is a big pond presenting scenic landscape.

Other structure	engineering	Graveyard
		Baolis, Well
		 Tank
		Cave

#### 4. Property Use

#### ABANDONED / IN USE $\sqrt{}$

Present	:	Source of water
Past	:	Source of water

5. Age (Source)

PERIOD YEARS	:	18 <sup>th</sup> Century AD
Precise date of Construction Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

### 6. Ownership / Level of Protection

#### SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:

<ul> <li>WITH PERSONS Patron Architect / Engineer Any other (specify)</li> <li>8. Statement of Significance</li> <li>Architectural Archaeological Historical Religious Any other (specify)</li> </ul>	:			
SEC	<u>CTION II: [</u>	DESCRIPT	ION	
9. Physical Descr	ription	and	Decorative	Features
<ul> <li>Context √ Urban / Rural Setting Surroundings         </li> </ul>	Urbar Stan	n Setting d in Isolat	ach extra sheet if ion a Landscape / S	
<ul> <li>Quantification Area Dimension (L x B x</li> <li>H) Number of Blocks Number of Storys</li> </ul>	:			(m / cm/ feet / inch)
<ul> <li>Spatial Organization Orientation Plan Allocation of Spaces</li> </ul>	: Pillin( : :	g of Plaste	r and Discoloratio	วท
<ul> <li>ARCHITECTURAL STYLE</li> <li>Ornamentation         <ul> <li>Exteriors</li> <li>Interiors</li> <li>Movable Collections</li> </ul> </li> <li>Any Other (specify)</li> </ul>	:			
10. Construction Technology	y			

**Structural System** : Pond having a Beautiful Landscape.

**Building Techniques** : Material of : Construction

### 11. Condition Assessment

In General

Good / Fair Good

 Sig
Sei
Da

n of Deterioration rious Deterioration Danger of Disappearance

### In Brief (Attach extra sheet if necessary):

Pilling of plaster and discoloration

# 12. Threats to the Property

Natural
 Negliger
Vandalis
Urban P

nce sm ressures

## **SECTION III:** REFERENCES

## **13. Reference Sources** (published and unpublished textual details)

14. Photographs	
(attach list as	in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals
etc.)	
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENT S	COMMENTS