

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/CRG-090

1. Name	SECTION I: IDENTIFICATION
Present Past Other Name (if any):	: Shiv Mandir :
2. Location	
LONGITUDE 74°54'E	LATITUDE 24°32'N
Address	Near, Vijay Stambh, Chittaurgarh
	: Village (village code)
	Post: ChittaurgarhDistrict: ChittaurgarhState: RajasthanPIN: 312001
Approach district	: The Temple is situated near by Vijay Stambh at Chittaurgarh fort in Chittaurgarh. It is 6km away from Chittaurgarh bus stand. It is well connected by regular bus services.
3. Property Type	
Buildings Palace √ Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structures Other Structures Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote: The temple is in a ruined state. It is not functional 'Shivlinga' placed in the 'Garbha griha'Public square Park or garden Graveyard Baolis, Well Tank CaveNote: The temple is in a ruined state. It is not functional 'Shivlinga' placed in the 'Garbha griha'

4. Property Use

		ABANDONED√ / IN USE
Present Past	:	Religious
5. Age (Source)		
PERIOD YEARS	:	14 th Century AD
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: :	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt.	:	
Private	:	
Any other (Please specify) Name Address	:	
Phone	:	
7. Association		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	:	
8. Statement of Significance		

√ ArchitecturalArchaeologicalHistorical

Religious
Any other (specify)

SECTION II: DESCRIPTION

:

9. Physical Description and Decorative Features

•	Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The temple is oriented East/West and faces the East.
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections y Other (specify)	- - - - -	

10. Construction Technology

Structural System	:	Temple made up of stone.
Building Techniques	:	
Material of Construction	:	Stone

11. Condition Assessment

In General

Good√ / Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Badly damaged 12. Threats to the Property

 Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attach list as in page C in some of multiple photographe)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS