

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/CRG-097 **SECTION I: IDENTIFICATION** 1. Name Present Mandir **Past** Other Name (if any): 2. Location **LONGITUDE** 74°54'E LATITUDE 24°32'N Address Shiv Mandir, Vijay Stambh Village (village code) **Post:** Chittaurgarh **District:** Chittaurgarh State: Rajasthan **PIN**: 312001 Approach district The Temple is situated near by Vijay Stambh at Chittaurgarh fort in Chittaurgarh. It is 6km away from Chittaurgarh bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Palace Wall Temple Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: The Temple is in a ruined structures state. Upper structure of the Public square temple is missing. Bridge Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use				
4. 1 Topcity 030		ABANDONED√ / IN USE		
Present Past 5. Age (Source)	:	Religious		
		4.40		
PERIOD YEARS	:	14 th Century AD		
Precise date of Construction	:			
Completion	:			
Subsequent changes Destruction / Demolition	:			
Destruction / Demolition	٠			
6. Ownership / Level of Protection	on			
•		SINGLE /MULTIPLE :		
Public: Archaeological Survey of	:			
India / State Archaeology	•			
Department / Any Other (Please				
specify)state Govt.				
Private	:			
Any other (Please specify)	:			
Name	:			
Address Phone	•			
FIIONE	•			
7. Association				
WITH EVENTS				
In History	:			
In Rituals	:			
In Building Construction	:			
Any other (specify)	:			
WITH PERSONS				
Patron Architect / Engineer	:			
Any other (specify)	:			
Any other (specify)	•			
8. Statement of Significance				
√ Architectural				
Archaeological				
Historical				

	Religious Any other (specify)	:			
SECTION II: DESCRIPTION 9. Physical Description and Decorative Features					
 Context Urban √/ Rural Setting Surroundings 			* Drawings (Attach extra sheet if necessary)		
	ourroundings		Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)		
	Number of Blocks Number of Storys	:	01 01		
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The temple is oriented East/West and faces the East.		
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : : : : : : : : : : : : : : : : : : :			
10.	. Construction Technology				

Ruined temple made up of stone.

Structural System Building Techniques Material of Construction Stone,

11. Condition Assessment	
In General	Good / √Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra sheet	if necessary):
Dilapidated condition	
12. Threats to the Property	
	√ NaturalNegligenceVandalismUrban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS