

#### INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

### **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: RJ/CRG-103 **SECTION I: IDENTIFICATION** 1. Name Present Surang Gate **Past** Other Name (if any): 2. Location **LONGITUDE** 74°54'E LATITUDE 24°32'N Address Gau kund ,chittaurgarh Village (village code) **Post:** Chittaurgarh **District:** Chittaurgarh State: Rajasthan **PIN**: 312001 Approach district The Gateway is situated at chittaurgarh fort in Chittaurgarh. It is well connected by regular bus services. It is 6km away from bus stand chittaurgarh. 3. Property Type Religious structures Other Structures **Buildings** Palace Temple Wall Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: The gateway is in ruined structures state. Side walls are damaged. Public square Stones and plaster scattered all Bridge Tunnel Park or garden over the place. Graveyard Other engineering structure Baolis, Well Tank Cave

		ABANDONED / IN USE	V
Present		Gateway	
Past	:	Gateway	
	-		
Age (Source)			
ERIOD		15 <sup>th</sup> century AD	
EARS	:	To century 715	
Precise date of Construction	:		
Completion	:		
Subsequent changes	:		
Destruction / Demolition	:		
. Ownership / Level of Protection	on		
		SINGLE /MULTIPLE :	
Public: Archaeological Survey of	:		
India / State Archaeology			
Department / Any Other (Please			
specify)state Govt.			
Private	:		
Any other (Please specify)	:		
lame	:		
Address	:		
Phone	:		
. Association			
WITH EVENTS			
In History	:		
In Rituals	:		
In Building Construction	:		
Any other (specify)	:		
WITH PERSONS			
Patron	:		
Architect / Engineer	:		
Any other (specify)	:		
tary tares (epiterry)	-		
8. Statement of Significance			
Architectural			
Archaeological			
Historical			
Religious			

	Any other (specify)	: SEC	CTION II: DESCRIPTION
9.	Physical Description and De		
•	Context Urban √ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)
	Carroananigo		Stand in Isolation Integral part of a Landscape / Street / Complex
•	<b>Quantification</b> Area Dimension ( L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01 01
•	Spatial Organization Orientation	:	The Gateway is oriented North/South and faces the North.
	Plan Allocation of Spaces	:	
ΑF	RCHITECTURAL STYLE		
•	Ornamentation		
	Exteriors	:	
	Interiors	:	
_	Movable Collections	:	
Ar	ny Other (specify)	:	

# 10. Construction Technology

Passage made up of stone.

Structural System Building Techniques Material of Construction

Stone

11. Condition Assessment						
In General	Good√ / Fair					
	Sign of Deterioration Serious Deterioration Danger of Disappearance					
In Brief (Attach extra sheet if necessary):						
<b>B</b> adly damaged.						
12. Threats to the Prope	erty					
	<ul><li>√ Natural</li><li>Negligence</li><li>Vandalism</li><li>Urban Pressures</li></ul>					

## **SECTION III:** REFERENCES

### 13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS