

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/CRG-195

SECTION I : IDENTIFICATION 1. Name			
Present Past Other Name (if any):	: Banjaran Ki Chhatri :		
2. Location			
LONGITUDE 74° 54' E Address	LATITUDE 24°32' N Near Badi Talab, Gang	grar	
Approach		Gangrar District: Chittaurgarh PIN: 312901 ted Badi Talab in Chittaurgarh. nittaurgarh bus stand. It is well	
3. Property Type			
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures Wall Gateway Pillar ✓ Others (specify) Chhatri	
Engineering structure Bridge Tunnel	Open space and related structures Public square Park or garden	Note: The Chhatri is in a dilapidated state. The dome is mutilated and full of Vegetational growth. It	

Other engineering structure	Graveyard		
	Baolis, Well		
	Tank		
Ē	Cave	stands on an platform.	elevated
4. Property Use			
	ABANDONE	D / IN USE $$:	
Present Past	: Chhatri : Memorial		
5. Age (Source)			
PERIOD	: 18 th Century AD		
YEARS	:		
Precise date of Construction	n :		
Completion	:		
Subsequent changes			
Destruction / Demolition	·		
6. Ownership / Level of Pro	tection		
	SINGLE /M	ULTIPLE :	
Public : Archaeological Surve	ev :		
of India / State Archaeology	5		
Department / Any Other			
(Please specify)			
Private	:		
Any other (Please specify) Name			
Address	:		
Phone	:		
7. Association			
WITH EVENTS			
In History	:		
In Rituals	:		
In Building Construction	1:		
Any other (specify) WITH PERSONS 	:		

Patron	:
Architect / Engineer	:
Any other (specify)	:

8 Statement of Significance

8. 9	Statement of Signi	ficance					
√	Architectural Archaeological Historical Religious		Ρ	ointed	and open	ing	
	Any other (specify)		:				
		<u>SEC</u>	TIC	<u>)n II: </u> [DESCRIPT	TION	
9.	Physical	Descr	ipti	on	and	Decorative	Features
	Context √ Urban / Rural Se	tting			wings (At n Setting	tach extra sheet i	f necessary)
Surroundings					d in Isolat ral part of		Street / Complex
• H)	Quantification Area Dimension (I	_ x B x	:				(m / cm/ feet / inch)
,	Number of Blocks Number of Storys		:	01 01			
•	Spatial Organizati Orientation	on	:	The (East	Chhatri is	oriented East –V	Vest and faces the
	Plan Allocation of Space	es	:				
<u>AR</u>	CHITECTURAL ST	YLE					
•	Ornamentation Exteriors		:				
	Interiors Movable Collection	S	:				

•	Ornamentation	
	Exteriors	
	Interiors	
	Movable Collections	
Ar	ny Other (specify)	

10. Construction Technology

Structural System	:	Indo – Persian
Building Techniques	:	Arcuate system
Materialof Construction	:	Stone

11. Condition Assessment

In General

,

Good / Fair Good

3	
3	
Ιг	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Badly damaged

12. Threats to the Property

N	
N	
۱v	
U	

latural legligence /andalism Irban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
(attach list as	in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals
etc.)	
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENT S	COMMENTS