



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/CRG - 111

SECTION I: IDENTIFICATION

1. Name

Present : Kali Bawari

Past :

Other Name (if any): :

2. Location

LONGITUDE 74° 54' E

LATITUDE 24° 32' N

Address : Kali Bawari, Gangrar

: **Village (village code)**

Post: Gangrar

District: Chittaurgarh

State: Rajasthan

PIN: 312901

Approach : The Bawari is situated near by Gangrar at Chittaurgarh fort in Chittaurgarh. It is 22 Km away from Chittaurgarh Bus stand. It is well connected by regular

bus services.

3. Property Type

<i>Buildings</i>		<i>Religious structures</i>		<i>Other Structures</i>	
<input type="checkbox"/>	Palace	<input type="checkbox"/>	Temple	<input type="checkbox"/>	Wall
<input type="checkbox"/>	Fort	<input type="checkbox"/>	Mosque	<input type="checkbox"/>	Gateway
<input type="checkbox"/>	Citadel	<input type="checkbox"/>	Minar	<input type="checkbox"/>	Pillar
<input type="checkbox"/>	Govt. building	<input type="checkbox"/>	Church	<input type="checkbox"/>	Others (specify)
<input type="checkbox"/>	Railway station	<input type="checkbox"/>	Monastery		
<input type="checkbox"/>	Defence building	<input type="checkbox"/>	Stupa		<i>Bawari</i>
<input type="checkbox"/>	Industrial building	<input type="checkbox"/>	Tomb, Mausoleum		
<input type="checkbox"/>	Other public buildings				
<input type="checkbox"/>	Residential building				
<i>Engineering structure</i>		<i>Open space and related structures</i>		Note: The step well is in a ruined state. It is cladded with rubble masonry. The well is abandoned and full of vegetation growth	
<input type="checkbox"/>	Bridge	<input type="checkbox"/>	Public square		
<input type="checkbox"/>	Tunnel	<input type="checkbox"/>	Park or garden		
<input type="checkbox"/>	Other engineering structure	<input type="checkbox"/>	Graveyard		
		<input type="checkbox"/>	Baolis, Well		
		<input type="checkbox"/>	Tank		
		<input type="checkbox"/>	Cave		

4. Property Use

ABANDONED / IN USE

: ✓

Present :

Past :

5. Age (Source)

PERIOD : 15th Century AD

YEARS :

Precise date of Construction :

Completion :

Subsequent changes :

Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :

Private :

Any other (Please specify) :

Name :

Address :

Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :

- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	: step well made up of rubble masonry
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

- **Context** * **Drawings** (Attach extra sheet if necessary)
 - Urban / Rural Setting** Urban Setting
 - Surroundings**
 - Stand in Isolation**
 - Integral part of a Landscape / Street / Complex**

- **Quantification**

Area Dimension (L x B x H) :

(m / cm/ feet / inch)

Number of Blocks : 01

Number of Storys : 01

- **Spatial Organization**

Orientation : The Bawari is oriented east – west and faces the east.

Plan :

Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**

Exteriors :

Interiors : Cladded with rubble masonry

Movable Collections :

Any Other (specify) :

10. Construction Technology

Structural System : Well cladded with rubble masonry

Building Techniques :

Material of Construction : Rubble masonry

1. Condition Assessment

In General **Good / Fair** Good

√	Sign of Deterioration
	Serious Deterioration
	Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Dilapidated

12. Threats to the Property

√	Natural
	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

**Serial No.: RJ/CRG -
189**

SECTION I : IDENTIFICATION

1. Name

Present : Sarneshwar mahadev mandir Ka Gate-2
Past :
Other Name (if any): :

2. Location

LONGITUDE 74° 54' E

LATITUDE

24° 32' N

Address : Sarneshwar mahadev mandir, Gangrar

: **Village (village code)**

Post : Gangrar

District: Chittourgarh

State : Rajasthan

PIN: 312901

Approach : The Gate is situated in Sarneshwar mahadev mandir, Gangrar in Chittourgarh district. It is 22 Km away from Chittourgarh Bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

<input type="checkbox"/>	Palace
<input type="checkbox"/>	Fort
<input type="checkbox"/>	Citadel
<input type="checkbox"/>	Govt. building
<input type="checkbox"/>	Railway station
<input type="checkbox"/>	Defence building
<input type="checkbox"/>	Industrial building
<input type="checkbox"/>	Other public buildings
<input type="checkbox"/>	Residential building

Religious structures

<input type="checkbox"/>	Temple
<input type="checkbox"/>	Mosque
<input type="checkbox"/>	Minar
<input type="checkbox"/>	Church
<input type="checkbox"/>	Monastery
<input type="checkbox"/>	Stupa
<input type="checkbox"/>	Tomb, Mausoleum

Other Structures

<input type="checkbox"/>	Wall
<input checked="" type="checkbox"/>	Gateway
<input type="checkbox"/>	Pillar
<input type="checkbox"/>	Others (specify)

Engineering structure

<input type="checkbox"/>	Bridge
--------------------------	--------

Open space and related structures

<input type="checkbox"/>	Public square
--------------------------	---------------

Note: The gateway has multiple arch opening. It is in a ruined state. Beautiful corning on the door- lintel and 'Dwar-Shakas.

<input type="checkbox"/>	Tunnel	<input type="checkbox"/>	Park or garden
<input type="checkbox"/>	Other engineering structure	<input type="checkbox"/>	Graveyard
		<input type="checkbox"/>	Baolis, Well
		<input type="checkbox"/>	Tank
		<input type="checkbox"/>	Cave

Side walls of the gateway has been damaged.

4. Property Use

ABANDONED / IN USE

: √

Present : Gateway
Past : Gateway

5. Age (Source)

PERIOD : 18th Century AD

YEARS :

Precise date of Construction :

Completion :

Subsequent changes :

Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology
Department / Any Other (Please
specify)

Private :

Any other (Please specify) :

Name :

Address :

Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :

- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	: Multiple arch opening
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	

	Religious	
	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

- **Context** * **Drawings** (Attach extra sheet if necessary)
 - Urban / Rural Setting** Urban Setting
 - Surroundings**
 - Stand in Isolation**
 - Integral part of a Landscape / Street / Complex**

- **Quantification**
 - Area Dimension (L x B x H) : (m / cm/ feet / inch)
 - Number of Blocks :
 - Number of Storys :

- **Spatial Organization**
 - Orientation : The gate is oriented north – south and faces the south.
 - Plan :
 - Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
 - Exteriors : Decorative pattern on the 'Dwar-shakas'.
 - Interiors :
 - Movable Collections : No

Any Other (specify) :

10. Construction Technology

Structural System : Indo- Persian
Building Techniques : Arcuate system
Material of Construction : Stone

1. Condition Assessment

In General **Good / Fair** Good

<input checked="" type="checkbox"/>	Sign of Deterioration
<input type="checkbox"/>	Serious Deterioration
<input type="checkbox"/>	Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Upper position is damaged, side walls have been broken pilling of plaster

12. Threats to the Property

<input checked="" type="checkbox"/>	Natural
<input type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input type="checkbox"/>	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS

