



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/CRG-123

SECTION I : IDENTIFICATION

1. Name

Present : Gateway
 Past :
 Other Name (if any): :

2. Location

LONGITUDE 74°54'E

LATITUDE 24°32'N

Address

Near jat a Shankar Mandir chittaurgarh

: **Village (village code)**

Post: Chittaurgarh

District: Chittaurgarh

State: Rajasthan

PIN: 312001

Approach district

: The Gateway is situated near by jata shankar Mandir at chittaurgarh fort in Chittaurgarh. It is 6km away from bus stand chittaurgarh. It is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: The gateway is completely damaged. Side walls are broken. The place is full of Vegetational growth.

4. Property Use

ABANDONED√ / IN USE

Present :
Past : Gateway

5. Age (Source)

PERIOD : 14th century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology
Department / Any Other (Please
specify)state Govt.
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- WITH EVENTS
 - In History :
 - In Rituals :
 - In Building Construction :
 - Any other (specify) :
- WITH PERSONS
 - Patron :
 - Architect / Engineer :
 - Any other (specify) :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural
<input type="checkbox"/>	Archaeological
<input type="checkbox"/>	Historical

<input type="checkbox"/>	Religious	:
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- | | | |
|--|--|--|
| Context | * Drawings (Attach extra sheet if necessary) | |
| Urban <input checked="" type="checkbox"/> / Rural <input type="checkbox"/> Setting | | |
| Surroundings | | |
| | Stand in Isolation | |
| | Integral part of a Landscape / Street / Complex | |

- | | | |
|------------------------------|---|-----------------------|
| Quantification | | |
| Area Dimension (L x B x H) | : | (m / cm/ feet / inch) |
| Number of Blocks | : | |
| Number of Storys | : | |

- | | | |
|-----------------------------|---|--|
| Spatial Organization | | |
| Orientation | : | The Gate is oriented East/West and faces the West. |
| Plan | : | |
| Allocation of Spaces | : | |

ARCHITECTURAL STYLE

- | | |
|----------------------------|---|
| Ornamentation | |
| Exteriors | : |
| Interiors | : |
| Movable Collections | : |
| Any Other (specify) | : |

10. Construction Technology

- | | | |
|---------------------------------|---|--------------------------|
| Structural System | : | Gateway made up of stone |
| Building Techniques | : | |
| Material of Construction | : | Stone |

11. Condition Assessment

In General

Good√ / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary): **Badly damaged**

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS

