I INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

Documentation format for Archaeological / Heritage Sites / Monuments


Serial No.:RJ/CRG -125

SECTION I: IDENTIFICATION

1. Name		
Present Past Other Name (if any):	: Chhatri : :	
2. Location		
LONGITUDE 74° 54' E	LATITUDE 24°32' N	
Address	: Sarneshwar Mahadev Mand	lir, Gangrar
	: Village (village code)	
	Post: Gangrar	District: Chittaurgarh
	State: Rajasthan	PIN : 312901
Approach	: The Chhatri is situated near b mandir, Gangrar at Chittaurgarh f 22 Km away from Chittaurgarh	ort in Chittaurgarh. It is

connected by regular bus services.

3. Property Type



4. Property Use

ABANDONED / IN USE $-\sqrt{}$

Present	:	Memorial
Past	:	Memorial

5. Age (Source)

PERIOD	:	18 th Century AD
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:
Private	:
Any other (Please specify)	:
Name	:
Address	:

7. Association

•	WITH EVENTS In History	:
	In Rituals	:
	In Building Construction	:
	Any other (specify)	:

• WITH PERSONS Patron : Architect / Engineer : Any other (specify) :

8. Statement of Significance

\checkmark	Architectural	: octagonal chhatri
	Archaeological	
	Historical	
	Religious	
	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

• Context

* Drawings (Attach extra sheet

Urban / Rural Setting

Surroundings

Urban Setting

Stand in Isolation

Integral part of a Landscape /

• Quantification

Area Dimension (L x B x :

H)

Number of Blocks	:01
Number of Storys	:01

• Spatial Organization

Orientation	:	The Chhatri is oriented east- we
Plan	:	
Allocation of Spaces	:	

ARCHITECTURAL STYLE

•	Ornamentation	
	Exteriors	: foliated arch opening
	Interiors	:
	Movable Collections	: no
Ar	ny Other (specify)	:


10. Construction Technology

Structural System	:	Indo -Persian.
Building Techniques	:	Arcuate system
Material of Construction	:	Stone etc.

1. Condition Assessment

In General


Good / Fair Good



In Brief (Attach extra sheet if necessary):

Mutilated dome, deposition of booth. formation of algae vegetation growth.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	

17. Listers

NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS