

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/CRG-139 **SECTION I: IDENTIFICATION** 1. Name Present Mandir **Past** Other Name (if any): 2. Location **LONGITUDE** 74°54'E LATITUDE 24°32'N Address Near, Kalika Mata Mandir, Chittaurgarh Village (village code) **Post:** Chittaurgarh **District:** Chittaurgarh State: Rajasthan **PIN**: 312001 Approach district The Temple is situated near by Kalika Mata Mandir in Chittarugarh district. It is 7km away from Chittaurgarh bus stand. It is well connected by regular bus services. 3. Property Type Religious structures Other Structures **Buildings** Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is the remains of a structures temple. Fallen parts are scattered all over the place. The temple has Bridge Public square minutely carved designs. Tunnel Park or garden Graveyard Other engineering structure Baolis, Well Tank Cave

4. Property Use	
	ABANDONED√ / IN USE
Present Past	: Religious
5. Age (Source)	
PERIOD YEARS	: 17 th Century AD :
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : :
6. Ownership / Level of Protection	
	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) Name	: : : :
Address	:
Phone	:
7. Association	
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance	: : : :
✓ ArchitecturalArchaeologicalHistoricalReligious	Intricately carved pattern

	<u> </u>	SEC	CTION II: DESCRIPTION	
9. Physical Description and Decorative Features				
 Context Urban √ Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary)		
Surroundings			Stand in Isolation Integral part of a Landscape / Street / Complex	
 Quantification Area Dimer 	tion nsion (L x B x H)	:	(m / cm/ feet / inch)	
Number of Number of		:	01 01	
Spatial Org Orientation Plan Allocation or		: : :	The temple is oriented East/West and faces the East.	
• Ornamenta Exteriors Interiors Movable Co Any Other (spe	ollections	: : : : : : : : : : : : : : : : : : : :		

Dilapidated temple made out of stone

Structural System
Building Techniques
Material of Construction Stone etc.

11. Condition Assessmer	nt
In General	Good /√ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra she	et if necessary):
Dilapidated condition	
12. Threats to the Proper	ty
	√ NaturalNegligenceVandalismUrban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS