



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/CRG-149

SECTION I : IDENTIFICATION

1. Name

Present : Shree Nag Chandeshwar Mahadev Mandir
Past :
Other Name (if any): :

2. Location

LONGITUDE 74°54'E

LATITUDE 24°32'N

Address

Shree Nag Chandeshwar Mahadev Mandir, Chittaurgarh

: **Village (village code)**

Post: Chittaurgarh

District: Chittaurgarh

State: Rajasthan

PIN: 312001

Approach district

: The Temple is situated near by Rampura Haveli at Chittaurgarh fort in Chittaurgarh. It is 7km away from Chittaurgarh bus stand. It is well connected regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: The temple can be approached by means of staircases. Mutilated image of 'Nandi' facing towards 'Garbhagriha'. Glazed marble tiles have been used on the walls.

4. Property Use

ABANDONED / IN USE

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 16th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt.
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	Temple made of stone.
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	

Religious
 Any other (specify) :

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- Context** : * Drawings (Attach extra sheet if necessary)

Urban Rural Setting

Surroundings

Stand in Isolation

Integral part of a Landscape / Street / Complex
- Quantification**

Area Dimension (L x B x H) : (m / cm/ feet / inch)

Number of Blocks : 01

Number of Storys : 01
- Spatial Organization**

Orientation : The temple is oriented East/West and faces the East.

Plan :

Allocation of Spaces :

ARCHITECTURAL STYLE

- Ornamentation**

Exteriors : Pointed with pink colour.

Interiors : Glazed marble tiles on the walls.

Movable Collections : Ritualistic objects.

Any Other (specify) :

10. Construction Technology

- Structural System** : Indo-Persian

Building Techniques :

Material of Construction : Stone, marble.

11. Condition Assessment

In General

Good√ / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Mutilated image of 'Nandi'

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS