# LINDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

# Documentation format for Archaeological / Heritage Sites / Monuments


Serial No.: RJ/CRG - 159

## **SECTION I: IDENTIFICATION**

1. Name		
Present Past Other Name (if any):	: Kund :	
Other Name (if any): 2. Location	•	
LONGITUDE 74° 54' E	LATITUDE 24°32' N	
Address	: Sarneshwar Mahadev Mandir	, Gangrar
	: Village (village code)	
	Post: Gangrar	District: Chittaurgarh
	State: Rajasthan	<b>PIN:</b> 312901
Approach	: The Kund is situated near by mandir, Gangrar at Chittaurgarh f is 22 Km away from Chittaurgarh	ort in Chittaurgarh. It

connected by regular bus services.

#### 3. Property Type



4. Property Use

ABANDONED / IN USE  $-\sqrt{}$ 

Present	:	
Past	:	Religious

5. Age (Source)

PERIOD	:	18 <sup>th</sup> Century AD
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

:

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:
Private	:
Any other (Please specify)	:
Name	:
Address	:

## 7. Association

•	WITH EVENTS In History	:
	In Rituals	:
	In Building Construction	:
	Any other (specify)	:
•	WITH PERSONS	
	Detren	

Patron	:
Architect / Engineer	:
Any other (specify)	:

# 8. Statement of Significance

$\checkmark$	Architectural	: Rectangular 'Kund' made up of rubble masonry.
	Archaeological	
	Historical	
	Religious	
	Any other (specify)	:

# SECTION II: DESCRIPTION

9. Physical Description and Decorative Features \_\_\_\_\_

•	Context	* Drawings (Attach extra sheet if necessary)
	Urban / Rural Setting	Urban Setting
	Surroundings	
		Stand in Isolation
		Integral part of a Landscape / Street / Complex
•	Quantification	
•	quantinoution	
	Area Dimension (L x B x H) :	
		(m / cm/ feet / inch

Number of Blocks	:	01
Number of Storys	:	01

I)

# • Spatial Organization

Orientation	: The Kund is oriented East- West and faces the	East.
Plan	:	
Allocation of Spaces	:	

# ARCHITECTURAL STYLE

Ornamentation	
Exteriors	:
Interiors	:
Movable Collections	:
Any Other (specify)	:

# **10. Construction Technology**


Structural System	:	Rectangular 'Kund' made up of rubble stone masonry
-------------------	---	--

Building Techniques:Material of Construction:Rubble masonry

### 1. Condition Assessment

In General Good


Good / Fair Good



In Brief (Attach extra sheet if necessary):

**Badly damaged** 

**12. Threats to the Property** 



#### **SECTION III:** REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs (attach list as in page 6, in case of multiple photographs) Photo Reference CAPTION 15. Audio / Video (related to rituals / performance / festivals etc.) Reference DESCRIPTION 16. Maps/Plans/Drawings

NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS