LINDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments


Serial No.: RJ/CRG - 162

SECTION I: IDENTIFICATION

1. Name		
Present Past Other Name (if any):	: Kund : :	
2. Location		
LONGITUDE 74° 54' E	LATITUDE 24°32' N	
Address	: Sarneshwar Mahadev r	nandir, Gangrar
	: Village (village co	ode)
	Post: Gangrar State: Rajasthan	District: Chittaurgarh PIN: 312901
Approach	: The kund is situated nea mandir, Gangrar at Chittaurg 22 Km away from Chittaur	garh fort Chittaurgarh . It is

connected by regular bus services.

3. Property Type



4. Property Use

ABANDONED / IN USE $-\sqrt{}$

Present	:	
Past	:	religious

5. Age (Source)

PERIOD	:	18 th Century AD
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

:

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:
Private	:
Any other (Please specify)	:
Name	:
Address	:

7. Association

•	WITH EVENTS In History	:
	In Rituals	:
	In Building Construction	:
	Any other (specify)	:

- WITH PERSONS Patron Architect / Engineer :
 - Any other (specify) :

:

8. Statement of Significance

\checkmark	Architectural	: Rectangular 'Kund'
	Archaeological	
	Historical	
	Religious	
	Any other (specify)	:
]	

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

•	Context		* Drawings (Attach extra sheet if ne	cessary)
	Urban / Rural Setting		Urban Setting	
	Surroundings			
			Stand in Isolation	
			Integral part of a Landscape / Stre	et / Complex
•	Quantification			
	Area Dimension (L x B x H)	:		
				(m / cm/ feet / inch)
	Number of Blocks	:		
	Number of Storys	:		

• Spatial Organization

Orientation	: The Kund is oriented east- west and faces the east.
Plan	:
Allocation of Spaces	:

ARCHITECTURAL STYLE

•	Ornamentation		
	Exteriors	:	
	Interiors	:	
	Movable Collections	:	No
Any Other (specify)			

10. Construction Technology

Structural System	:	Rectangular 'Kund'	made up of stone
-------------------	---	--------------------	------------------


Building Techniques :

Material of Construction : Stone etc.

1. Condition Assessment

In General


Good / Fair Good



In Brief (Attach extra sheet if necessary):

Badly damaged

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs (attach list as in page 6, in case of multiple photographs) Photo Reference CAPTION 15. Audio / Video (related to rituals / performance / festivals etc.) Reference DESCRIPTION

17. Listers

NAME	NAME		
18. Reviewers			
NAME	NAME		
COMMENTS	COMMENTS		