


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/CRG - 165

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any):	: Chhatri : :
2. Location	
LONGITUDE 74° 54' E	LATITUDE 24°32' N
Address	: Sarneshwar mahadev mandir, Gangrar
	: Village (village code)
	Post : GangrarDistrict: ChittaurgarhState : RajasthanPIN: 312901
Approach	: The chhatri is situated near by Sarneshwar mahadev mandir,at Gangrar in Chittaurgarh district. It is 22 Km away from Chittaurgarh Bus stand. It is well connected by regular bus services.

3. Property Type



4. Property Use

		ABANDONED / IN USE \checkmark
Present Past	:	: Memorial Memorial
5. Age (Source)		
PERIOD YEARS	:	18 th Century AD
Precise date of Construction Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private	:	
Any other (Please specify) Name	÷	
Address	÷	
Phone	:	
7. Association		
WITH EVENTS		
In History In Rituals	:	
In Building Construction		
Any other (specify)	:	
WITH PERSONS Patron		
Architect / Engineer	÷	
Any other (specify)	1	
8. Statement of Significance		
Architectural	: fc	bliated arch opening

Architectural

: foliated arch opening

Archaeological

	Historical
	Religious
	Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _

:

•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Setting
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Chhatri is oriented north -south and faces the north.
<u>AF</u> •	RCHITECTURAL STYLE Ornamentation Exteriors	:	Foliated arch opening
Ar	Interiors Movable Collections ny Other (specify)	: : :	No

10. Construction Technology

Structural System	:	Indo -Persian.
Building Techniques	:	Arcuate system
Material of Construction	:	Stone etc.

1. Condition Assessment

In General


Good / Fair Good

√ s

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary): Discoloration, mutilated dome, deposition of booth and vegetation growth

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS