

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: RJ/CRG-170 **SECTION I: IDENTIFICATION** 1. Name Present Vishavakarma Mandir Past Other Name (if any): 2. Location **LONGITUDE** 74° 54' E LATITUDE 24°32' N Near Kila, Gangra Address : Village (village code) Gangrar Post: Gangrar **District:** Chittaurgarh **State:** Rajasthan **PIN:** 312901 The Temple is situated at Gangrar in Chittaurgarh. **Approach** It is 22 Km from Chittaurgarh bus stand. It is well connected by regular bus services. 3. Property Type **Other Structures Buildings** Religious structures Temple Palace Wall Fort Mosque Gateway Minar Pillar Citadel Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb. Mausoleum Other public buildings Residential building Engineering structure Open space and related **Note:** This is a temple structures dedicated to Vishavakarma Jee. The facade of the Public square Bridge temple is simple with foliated Tunnel Park or garden

| Other engineering structure  4. Property Use   | Graveyard<br>Baolis, Well<br>Tank<br>Cave | arch opening. It has domical superstructure with inverted lotus type of cresting. It has decorative and painted |  |  |  |  |  |
|--|---|---|--|--|--|--|--|
|  | ABANDONED /IN USE : √                     |   |  |  |  |  |  |
| Present<br>Past  | : Religious<br>: Religious                |   |  |  |  |  |  |
| 5. Age (Source)  |   |   |  |  |  |  |  |
| PERIOD<br>YEARS  | : 20 <sup>th</sup> Century AD<br>:        |   |  |  |  |  |  |
| Precise date of Construction<br>Completion<br>Subsequent changes<br>Destruction / Demolition               | :<br>:<br>:                               |   |  |  |  |  |  |
| 6. Ownership / Level of Prote  | ction                                     |   |  |  |  |  |  |
|  | SINGLE<br>/MULTIPLE :                     |   |  |  |  |  |  |
| <b>Public</b> : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) | :   |   |  |  |  |  |  |
| Private Any other (Please specify)   | :   |   |  |  |  |  |  |
| Name   | :   |   |  |  |  |  |  |
| Address<br>Phone   | :   |   |  |  |  |  |  |
| 7. Association   |   |   |  |  |  |  |  |
| WITH EVENTS  |   |   |  |  |  |  |  |
| In History<br>In Rituals   | :   |   |  |  |  |  |  |
| III Nituais  | •   |   |  |  |  |  |  |

Any other (specify) **WITH PERSONS Patron Architect / Engineer** Any other (specify) 8. Statement of Significance Architectural Dome is surmounted by inverted lotus type of pinnacle Archaeological Historical Religious Any other (specify) **SECTION II: DESCRIPTION** 9. **Physical** Description and Decorative **Features** \* Drawings (Attach extra sheet if necessary) Context √ Urban / Rural Setting **Urban Setting Surroundings** Stand in Isolation Integral part of a Landscape / Street / Complex Quantification Area Dimension ( L x B x : (m / cm/ feet / inch) H) Number of Blocks 01 Number of Storys 01 Spatial Organization Orientation The temple is oriented East-West and faces the West Plan Allocation of Spaces ARCHITECTURAL STYLE Ornamentation **Exteriors** Interiors Image of deity is placed on raised platform Ritualistic objects Movable Collections

In Building Construction

**Any Other** (specify)

| 10. Construction Technology                                   |  |  |  |  |
|---|--|--|--|--|
| Structural System Building Techniques Materialof Construction | <ul><li>Indo – Persian</li><li>Arcuate system</li><li>Stone and marble</li></ul> |  |  |  |
| 11. Condition Assessment                                      |  |  |  |  |
| In General Go   | od / Fair Good   |  |  |  |
|   | Sign of Deterioration  ✓ Serious Deterioration  Danger of Disappearance          |  |  |  |
| In Brief (Attach extra sheet if necessary):                   |  |  |  |  |
| Pilling of plaster and discoloration                          |  |  |  |  |
| 12. Threats to the Property                                   |  |  |  |  |
|   | Natural Negligence √ Vandalism Urban Pressures                                   |  |  |  |

## **SECTION III:** REFERENCES

## 13. Reference Sources (published and unpublished textual details)

| 14. Photographs         |   |
|-------------------------|---|
|                         | ach list as in page 6, in case of multiple photographs) |
|                         | aon not do in pago o, in odos or manipio priotographo,  |
| Photo Reference         |   |
|                         |   |
| CAPTION                 |   |
| -                       |   |
| 15. Audio / Video       |   |
| 10. Addio / Video       | (related to rituals / performance / festivals           |
|                         | (related to rituals / performance / restivals           |
| etc.)                   |   |
| •                       |   |
| Reference               |   |
|                         |   |
| DESCRIPTION             |   |
|                         |   |
| 16. Maps/Plans/Drawings |   |
|                         |   |
|                         |   |
|                         |   |
|                         |   |
| 4-1-4                   |   |
| 17. Listers             |   |
|                         |   |
| NAME                    | NAME  |
|                         |   |
| 18. Reviewers           |   |
| 10.17641644613          |   |
|                         |   |
| NAME                    | NAME  |
|                         | NAME  |
|                         | NAME COMMENTS   |