



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/DSA-038

SECTION I : IDENTIFICATION

1. Name

Present : Kherali Darwaja
Past :
Other Name (if any): :

2. Location

LONGITUDE

LATITUDE

Address

Bhandarej, Dausa

: **Village (village code)**

Post : Bhandarej

District: Dausa

State : Rajasthan

PIN: 303501

Approach

: The Gateway is situated at Bhandarej in Dausa city. It is 11 Km away from Dausa bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|-------------------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input checked="" type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: It is a large massive gateway with circular arch opening and is surmounted by Kangura pattern.

4. Property Use

ABANDONED / IN USE :

Present : Gateway
Past : Gateway

5. Age (Source)

PERIOD : 18th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** : Gateway
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	Circular arch
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban / Rural Setting
Surroundings

* **Drawings** (Attach extra sheet if necessary)
Urban

Stand in Isolation
Integral part of a Landscape / Street / Complex
- **Quantification**
Area Dimension (L x B x H) :

(m / cm/ feet / inch)

Number of Blocks : 01
Number of Storys : 01
- **Spatial Organization**
Orientation : The Gateway is oriented East - West direction and faces West.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Kangura pattern.
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Indo - Persian
Building Techniques : Trabeate system
Material of Construction : Bricks & stone

11. Condition Assessment

In General	Good / Fair
	Good

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

Plaster peeling off.

12. Threats to the Property

<input type="checkbox"/>	Natural
<input type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input type="checkbox"/>	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS