



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No: RJ\JDP-085

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Mandir  
 Past :  
 Other Name (if any):

#### 2. Location

LONGITUDE 73°52'E

LATITUDE 27°37'N

#### Address

Betwasia Tahasil Osian Jodhpur

: **Village (village code)** Betwasia

**Post:** Betwasia

**District:** Jodhpur

**State:** Rajasthan

**PIN:** 342303

#### Approach district

: The khandar is situated at Betwasia in Jodhpur district. It is 70km away from Jodhpur bus stand. it is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)  
*Khandar*

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** This dilapidated temple complex must once have been on elaborate one. There are some small shrines with diframgmented mandapas roofs and in some cases even the sanctum. There are some small stone blocks and shrines with carved images of god and goddess.

#### 4. Property Use

---

ABANDONED√ / IN USE

Present :  
Past :

#### 5. Age (Source)

---

PERIOD : 12<sup>th</sup> Century AD  
YEARS :

Precise date of Construction :  
Completion :  
Subsequent changes :  
Destruction / Demolition :

#### 6. Ownership / Level of Protection

---

SINGLE / MULTIPLE :

Public : Archaeological Survey of :  
India / State Archaeology :  
Department / Any Other (Please :  
specify)state Govt. :  
Private :  
Any other (Please specify) :  
Name :  
Address :  
Phone :

#### 7. Association

---

- WITH EVENTS
  - In History :
  - In Rituals :
  - In Building Construction :
  - Any other (specify) :
- WITH PERSONS
  - Patron :
  - Architect / Engineer :
  - Any other (specify) :

#### 8. Statement of Significance

---

- |                                     |                |
|-------------------------------------|----------------|
| <input checked="" type="checkbox"/> | Architectural  |
| <input type="checkbox"/>            | Archaeological |
| <input type="checkbox"/>            | Historical     |
| <input type="checkbox"/>            | Religious      |

Any other (specify) :

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- **Context** : **\* Drawings** (Attach extra sheet if necessary)  
**Urban** ✓ / **Rural Setting**  
**Surroundings**  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H ) : (m / cm/ feet / inch)  
Number of Blocks : 01  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The khandar is oriented North/South and faces the North.  
Plan :  
Allocation of Spaces :

### **ARCHITECTURAL STYLE**

- **Ornamentation**  
Exteriors :  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### **10. Construction Technology**

---

- Structural System** : Indo Persian
- Building Techniques** : Arcuate system
- Material of Construction** : Stone and rubble masonry

## 11. Condition Assessment

---

In General

Good/ Fair✓

- |                                     |                         |
|-------------------------------------|-------------------------|
| <input type="checkbox"/>            | Sign of Deterioration   |
| <input type="checkbox"/>            | Serious Deterioration   |
| <input checked="" type="checkbox"/> | Danger of Disappearance |

### In Brief (Attach extra sheet if necessary):

The stone masonry off the surviving walls have got exposed to the vagaries of weather. The stone lintels have developed cracks and one facing apart.

---

## 12. Threats to the Property

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input checked="" type="checkbox"/> | Vandalism       |
| <input checked="" type="checkbox"/> | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**