

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No: RJ\JDP-117

SECTION I : IDENTIFICATION		
1. Name Present Past Other Name (if any):	: Gabai Talab :	
2. Location		
LONGITUDE 73°52'E	LATITUDE 27°37'N	
Address	Umednagar Jodhpur	
	: Village (village code)	Umednagar
	Post: Umednagar State: Rajasthan	District: Jodhpur PIN: 342305
Approach district		ted at Umednagar in Jodhpur ay from Jodhpur bus stand. it is ular bus services.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures Wall Gateway Pillar ✓ Others (specify) Talab
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic squarePark or gardenGraveyardBaolis, WellTankCave	Note: This is an elongated lake but doesn't seem to be a natural one. It has sharj cut edges and some postions have rubble ghat and enclosed section forming a lagoon.

4. Property Use

		ABANDONED / IN USE \checkmark
Present	:	Drinking water
Past	:	Drinking water
5. Age (Source)		
PERIOD YEARS	÷	16 th Century AD
	•	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	Govt of Rajasthan
India / State Archaeology	-	
Department / Any Other (Please		
• • •		
specify)state Govt.		
Private		
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
√ Architectural		
Archaeological		
Historical		

Religious

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

2

- * Drawings (Attach extra sheet if necessary) Context Urban $\sqrt{}$ Rural Setting Surroundings Stand in Isolation Integral part of a Landscape / Street / Complex Quantification • Area Dimension (L x B x H) : (m / cm/ feet / inch) Number of Blocks : Number of Storys : Spatial Organization • Orientation : The Talab is oriented East/West and faces the East. Plan : Allocation of Spaces ÷ **ARCHITECTURAL STYLE** Ornamentation Exteriors : Interiors **Movable Collections** Any Other (specify)
- **10.** Construction Technology

Structural System	:
Building Techniques	:
Material of Construction	:

11. Condition Assessment

In General

Good $\sqrt{}$ / Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Lacks general mentaince especially around the lake. However the water seems to be clean.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attack list as in page C in some of multiple shots more bar)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS