



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No: RJ\JDP-379

SECTION I : IDENTIFICATION

1. Name

Present : Jain Mandir
 Past :
 Other Name (if any):

2. Location

LONGITUDE 73°52'E

LATITUDE 27°37'N

Address

Trinwari Jodhpur

: **Village (village code)** Trinwari

Post: Trinwari

District: Jodhpur

State: Rajasthan

PIN: 342303

Approach district

: The Temple is situated at Tinwari in Jodhpur district. It is 50km away from Jodhpur bus stand. it is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: This is an elaborate temple complex with in a boundry wall. the wal and the entire structure are lime coated. The temple has a mukha Mandap followed by a mandapam which has a massive domical spire and is further connected to the

sanctum which has a shikhara
has a spire all the mandaps

4. Property Use

ABANDONED/ IN USE ✓

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 17th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology
Department / Any Other (Please
specify)state Govt.

Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- WITH EVENTS
 - In History :
 - In Rituals :
 - In Building Construction :
 - Any other (specify) :
- WITH PERSONS
 - Patron :
 - Architect / Engineer :
 - Any other (specify) :

8. Statement of Significance

Architectural

- | | | |
|--------------------------|---------------------|---|
| <input type="checkbox"/> | Archaeological | |
| <input type="checkbox"/> | Historical | |
| <input type="checkbox"/> | Religious | |
| <input type="checkbox"/> | Any other (specify) | : |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- | | | |
|---------------------------------------------------------|--|--------------------------------------------------------|
| Context | | * Drawings (Attach extra sheet if necessary) |
| Urban <input checked="" type="checkbox"/> Rural Setting | | |
| Surroundings | | |
| | | Stand in Isolation |
| | | Integral part of a Landscape / Street / Complex |

- | | | |
|-------------------------------|----|-----------------------|
| Quantification | | |
| Area Dimension (L x B x H) : | | (m / cm/ feet / inch) |
| Number of Blocks : | 01 | |
| Number of Storys : | 01 | |

- | | | |
|-----------------------------|---------------------------------------------------------|--|
| Spatial Organization | | |
| Orientation : | The Temple is oriented North/South and faces the North. | |
| Plan : | | |
| Allocation of Spaces : | | |

ARCHITECTURAL STYLE

- | | | |
|------------------------------|------------------------------------------------------------------------|--|
| Ornamentation | | |
| Exteriors : | It seems to be incomplete as there are bhadrikas but no figures in it. | |
| Interiors : | The shikhar has all the basic attribute. | |
| Movable Collections : | | |
| Any Other (specify) : | | |

10. Construction Technology

- | | | |
|---------------------------------|---|------------------------------|
| Structural System | | Jain –Indo Persian and Hindu |
| Building Techniques | : | Arcuate and Trabeate |
| Material of Construction | : | Stone, rubble, lime etc. |

11. Condition Assessment

In General

Good✓ / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

It lacks general maintenance. The lime coated Shikar excessive accumulation of soot and black deposits, so does the domes. The vicinity is quite unkept.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS