

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JDP-533

	S	ЕСТ	ION I : IDE	ENTIFICATION	
1. Name					
Present Past Other Name (if an	y):	:	Chhatri		
2. Location					
LC	DNGITUDE	73 ⁰	⁰ 52 ['] E	LATITUDE	27º 37 [°] N
Address		:		Talab, Jodhpur village code)	
			Post: J State: F	Iodhpur Rajasthan	District: Jodhpur PIN: 342001
Approach district		:	lt is 4kn		d at Ranisar Talab in Jodhpur. lodhpur bus stand. it is well s services.

3. Property Type



4. Property Use

		ABANDONED√ / IN USE
Present	:	
Past	÷	
	-	
5. Age (Source)		
PERIOD	:	
YEARS	:	
Precise date of Construction		
Completion		
Subsequent changes		
Destruction / Demolition	:	
	•	
6. Ownership / Level of Protection	<u>on</u>	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)state Govt.		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
• WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	Memorial
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
-		
8. Statement of Significance		

Architectural Archaeological

Domical superstructure

Historical	
Religious	
Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

•	ontext Irban √/ Rural Setting surroundings		* Drawings (Attach extra sheet if necessary)		
	Ganganango		Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)		
	Number of Blocks Number of Storys	:			
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :			
<u>A</u> F	CHITECTURAL STYLE				
• Ar	Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Canopied chhatr, Kangura pattern, foliated arch.		

10. Construction Technology

Structural System	:	Indo-persian
Building Techniques	:	Trabeate system
Material of Construction	:	Stone and plaster

11. Condition Assessment

In General	
------------	--

Good√ / Fair



Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface, breaking of structure 12. Threats to the Property

	Natural
	Negligence
\checkmark	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attach list as in page C in some of multiple photographe)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS