


INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JDP-539

	SECTION I : IDENTIFICATION
1. Name	
Present Past Other Name (if any):	: Bhim Kund :
2. Location	
LONGITUDE	73° 52' E LATITUDE 27° 37' N
Address	 Pachetia Hill, Jodhpur Village (village code)
Approach district	Post : Jodhpur District: Jodhpur State : Rajasthan PIN: 342001 : The Kund is situated at Pachetia Hill. It is 5km away from Lodhpur bus stand, it is well connected by regular
3. Property Type	from Jodhpur bus stand. it is well connected by regular bus services.
5.44	



4. Property Use

		ABANDONED√ / IN USE
Present	:	
Past	:	
5. Age (Source)		
PERIOD	:	16 th Century AD
YEARS	:	
Precise date of Construction		
Completion		
Subsequent changes		
Destruction / Demolition	÷	
6. Ownership / Level of Protection	on	
<u> </u>		SINGLE /MULTIPLE :
0 ,	:	
India / State Archaeology		
Department / Any Other (Please		
specify)state Govt.		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	Water resivour
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		

Architectural Archaeological

Water resivour

Historical	
Religious	
Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

•	Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Kund is oriented East/West and faces the East.
<u>AF</u>	CHITECTURAL STYLE Ornamentation		
	Exteriors Interiors Movable Collections	:	Kangura Pattern
An	y Other (specify)	:	

10. Construction Technology

Structural System	:	Indo-persia	an
Building Techniques	:	Trabeate sy	/stem
Material of Construction	:	Stone and	plaster

11. Condition Assessment

In General	
------------	--

Good√ / Fair



Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening and dust, dirt deterioration of surface. Algae formation. **12. Threats to the Property**



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attack list as in page C in some of multiple shots more bay)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS