

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JDP-547

SECTION I : IDENTIFICATION		
1. Name		
Present Past Other Name (if any): 2. Location	: Govt School :	
LONGITUDE	73º 52' E LATITUDE 27º 37' N	
Address	: Near Gulab Bag Sagar Jodhpur	
	: Village (village code)	
	Post :JodhpurDistrict:JodhpurState :RajasthanPIN:342001	
Approach district	: The School is situated at Gulab Sagar in Jodhpur district. It is 3km away from Jodhpur bus stand. it is well connected by regular bus services.	

3. Property Type



4. Property Use $\sqrt{}$ **ABANDONED/ IN USE** Present School 2 Past School : 5. Age (Source) PERIOD 19th Century AD 2 YEARS 5 **Precise date of Construction** 2 Completion 5 Subsequent changes 5 **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify)state Govt. Private 3 Any other (Please specify) 2 Name 2 Address : Phone : 7. Association • WITH EVENTS In History 3 School In Rituals : In Building Construction 3 Any other (specify) 2 WITH PERSONS Patron 2 Architect / Engineer 2 Any other (specify) 2 8. Statement of Significance Architectural

Archaeological

Foliated arch

Historical
Religious
Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

:

•	Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01 01
•	Spatial Organization Orientation	:	The School is oriented North/South and faces the North.
	Plan Allocation of Spaces	:	
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections	:	Foliated arch, brackets, medallion.
An	y Other (specify)	:	

10. Construction Technology

Structural System	:	Indo-persian
Building Techniques	:	Trabeate system
Material of Construction	:	Red stone, brick and plaster

11. Condition Assessment

In General

Good√ / Fair

Si
S
D

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Plaster peeling off, blackening of surface.

12. Threats to the Property

Natural
Negligence
 Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attack list as in page C in some of multiple shots more bay)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS