



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-71

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Well  
Past :  
Other Name (if any): :

#### 2. Location

LONGITUDE 75° 4' E

LATITUDE 28° 13' N

#### Address

Mittal Colony, Chhawari Bazar, Jhunjhunu

: **Village (village code)**

**Post** : Jhunjhunu

**District**: Jhunjhunu

**State** : Rajasthan

**PIN**: 333001

#### Approach

: The well is situated near Chhawari Bazar

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)
- Well

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is a circular well topped by a square structure guarded by a octagonal pillars on each side. The pillars have dome on top and inverted lotus with a sifter on the stop. It rests on a high platform.

#### 4. Property Use

---

**ABANDONED / IN USE :** Abandoned

**Present** : Abandoned  
**Past** : Source of drinking water

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 20<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - ✓ **In Building Construction** : Used for the water related utilities.
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |                                     |
|-------------------------------------|---------------------|-------------------------------------|
| <input checked="" type="checkbox"/> | Architectural       | Has four domical octagonal pillars. |
| <input type="checkbox"/>            | Archaeological      |                                     |
| <input type="checkbox"/>            | Historical          |                                     |
| <input type="checkbox"/>            | Religious           |                                     |
| <input type="checkbox"/>            | Any other (specify) |                                     |



## 11. Condition Assessment

---

**In General**

**Good / Fair – good**

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

**In Brief (Attach extra sheet if necessary):**

Flaking at minor levels.

## 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**