



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-73

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Dinesh Ji Ki Haveli  
Past :  
Other Name (if any): :

#### 2. Location

LONGITUDE 75° 4' E

LATITUDE 28° 13' N

#### Address

Chhawari Bazar, Jhunjhunu

: **Village (village code)**

**Post** : Jhunjhunu

**District**: Jhunjhunu

**State** : Rajasthan

**PIN**: 333001

#### Approach

: The haveli is situated near chhawari bazaar.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)  
Haveli

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** A closed rectangular boundary house leads to interior with an arched doorway double pillared arched pavilion supported by interior rooms. It rests on a high platform bracketed balcony on the top is impressive.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Residence  
**Past** : Residence

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 19<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - ✓ **In History** : Residential place of Dinesji master.
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - ✓ **Any other (specify)** :

#### 8. Statement of Significance

---

|                                     |                     |   |
|-------------------------------------|---------------------|---|
| <input checked="" type="checkbox"/> | Architectural       | Was used as a dwelling house of people. Combination of Indi-Persian architecture. |
| <input type="checkbox"/>            | Archaeological      |   |
| <input type="checkbox"/>            | Historical          |   |
| <input type="checkbox"/>            | Religious           |   |
| <input type="checkbox"/>            | Any other (specify) |   |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 02  
Number of Storys : 02
  
- **Spatial Organization**  
Orientation : The Haveli is oriented East-West and faces the West.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Glazed arched pavilion on a high platform, rectangular in plan closed architure.  
Interiors : Pillared pavilion with rooms besides the open arena. Well in the vicinity.  
Movable Collections :  
**Any Other** (specify) : Jaali work on top panels of square doors and windows.

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcurate system
- Material of Construction** : Stone, lime plaster, mortar.

## 11. Condition Assessment

---

**In General**

**Good / Fair - good**

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

### **In Brief (Attach extra sheet if necessary):**

The back area is in ruins. Stones emerging out from the rubble. Haking of Limeplaster.

## 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**