

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1058

SECTION I: IDENTIFICATION 1. Name				
Present Past Other Name (if any):	: Tibrawala Ka Haveli : :			
2. Location				
LONGITUDE 75° 4' E	LATITUDE 28 ⁰ 13 ['] N			
Address	W-6 Gangiasar			
Approach		Gangiasar District: Jhunjhunu PIN: 333046 ed Gangiasar. It is 50km from Il connected by regular bus		
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar ✓ Others (specify) Haveli		
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: It is a grand Masonic structure embellished with beautiful Rajasthani frescos on the walls and chhajjas. The vault of the arch is aderned with beautiful Ala-gila paintings.		

4. Property Use	
	ABANDONED / IN USE: ABANDONED
Present Past	: Residential
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: 19 th century A.D. : : : : :
•	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name	: :
Address	:
Phone	:
7. Association	
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: : :
8. Statement of Significance	
 ✓ Architectural Archaeological Historical Religious Any other (specify) 	Dressed stone structure.

SECTION II: DESCRIPTION

9.	Physical Description and I	Decora	ative Feat	tures		
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Rural setting.			
	ourroundings			n Isolation part of a La	ındscape / S	Street / Complex
•	Quantification Area Dimension (L x B x F	· i				(m / am/fact / inah)
	Number of Blocks Number of Storys	: :	02 02			(m / cm/ feet / inch)
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The hav	eli is oriented	d North-sout	h and faces the north.
<u>AR</u>	CCHITECTURAL STYLE Ornamentation Exteriors	:	It has foliated arch opening. The walls and chhajjas aderned with Rajasthani frescos.			
An	Interiors Movable Collections y Other (specify)	: : :	adomod	, waa ragada	iai ii oocoo.	
10.	. Construction Technology	/				
	Structural System Building Techniques Material of Construction	: : :	Indo-Per Arcuate Brick, sto		ster.	
11.	Condition Assessment					
	In General	Good	/ Fair		Good	
	Sign of Deterioration Serious Deterioration Danger of Disappearance)				
In	Brief (Attach extra sheet if	neces	ssary):			
Dis	scoloration, peeling of plaste	er and b	olackenin	g.		

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS