

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1065

SECTION I: IDENTIFICATION 1. Name				
Present Past Other Name (if any):	: Mahavir Prasad Soni Kesher Ka Bh :	nawan		
2. Location				
LONGITUDE 75° 4' E	LATITUDE 28° 13' N			
Address	W-05 Gangiasar			
Approach	 Village (village code) Gangiasa Post : Gangiasar District: State : Rajasthan PIN: 333 The Bhawan is situated Gangiasa Jhunjhunu. And well connected services. 	Jhunjhunu 1046 ar. It is 50km from		
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Others Wall Gateway Pillar Others (Bhawan	specify)		
Engineering structure Bridge Tunnel Other engineering structure		an old structure in a state. It has a week II.		

4. Property Use		
		ABANDONED / IN USE : ABANDONED
Present Past	:	Residential
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : : : : : : : : : : : : : : : :	19 th century A.D.
6. Ownership / Level of Protection	<u>on</u>	
		SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private Any other (Please specify) Name Address Phone	: : : : : : : : : : : : : : : : : : : :	Mahavir Prasad Soni
7. Association		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: : : : : : : : : : : : : : : : : : : :	
8. Statement of Significance		
Architectural Archaeological Historical Religious Any other (specify)		

SECTION II: DESCRIPTION

9.	Physical Description and D	Decora	ative Features
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Rural setting
	Carrounanigs		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) :	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	: :	The haveli is oriented North-south and faces the north.
•	Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : : : : : : : : : : : : : : : : : : :	It is a dilapidated structure.
10.	Construction Technology	,	
11.	Structural System Building Techniques Material of Construction Condition Assessment	:	Indo-Persian Arcuate Brick and stone.
		Good	/ Fair Good
	Sign of Deterioration Serious Deterioration Danger of Disappearance		
In I	Brief (Attach extra sheet if	neces	ssary):
Dila	apidated		

12. Threats to the Property	
	✓ Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
•	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS