

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1081

1. Name	SECTION I: IDENTIFICATION	
Present Past Other Name (if any):	: Rai Mata ka Well :	
2. Location		
LONGITUDE 75° 4' E	LATITUDE 28 ⁰ 13 ['] N	
Address	Rai Mata Mandir, Nangiasar	
	: Village (village code) Post : Nangiasar State : Rajasthan	Nangiasar District : Jhunjhunu PIN : 333046
Approach	: The Well situated at Gar	ngiasar near bia-pass
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify) Well
Engineering structure Bridge Tunnel Other engineering structure	structures Superior S	Note: It is a well with circular shaft. There is a platform built around it with a pier-rafter arch marking the mouth.

4. Property Use		
		ABANDONED / IN USE: Abandoned
Present	:	Dried up
Past	:	Source of drinking water
		Tours or annual grants
5. Age (Source)		
PERIOD		
YEARS	:	15 th Century A.D.
Precise date of Construction	•	10 Octifuty A.D.
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	<u>n</u>	
		SINGLE /MULTIPLE :
Public: Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	•	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
 WITH PERSONS 		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9. Physical Description and	Decorative Features
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) Rural Setting Surroundings
ouougo	Stand in Isolation Integral part of a Landscape / Street / Complex
Quantification Area Dimension (L x B x F)	H) : (m / cm/ feet / inch)
Number of Blocks Number of Storys	:
Spatial Organization Orientation	: The Well is oriented East – West and faces South - North
Plan Allocation of Spaces	: :
• Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	: : :
10. Construction Technology	/
Structural System Building Techniques Material of Construction	: Corbelling : Bricks, cement
11. Condition Assessment	
In General	Good / Fair
Sign of Deterioration Serious Deterioration Danger of Disappearance	
In Brief (Attach extra sheet i	necessary):
Peeling paint; blackening & dis	scoloration.

✓	Natural
\	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS
LALIMINICIA I.3	CACIVITIES 1.3