

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN - 1164

1. Name	SECTION I : IDENTIFICATIO	N
Present Past Other Name (if any):	:	
2. Location		
LONGITUDE 75° 4' E	LATITUDE 28 ⁰ 13 ['] N	
Address	Ward No – 4, Chirawa.	
Approach 3. Property Type	 Village (village code) Post : Chirawa State : Rajasthan The school building is Basti. 	District: Jhunjhunu PIN: 333026 located at Chirawa near Balmiki
Buildings	Religious structures	Other Structures
Palace Fort Citadel ✓ Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Wall Gateway Pillar ✓ Others (specify) School
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic squarePark or gardenGraveyardBaolis, WellTankCave	Note: It is a large complex with a compound wall and front yard. It is a 2 storey modern structure, with lattice work on its terrace railings.

4. Property Use

		ABANDONED / IN USE : In use
Present	:	School
Past	:	Residence
5. Age (Source)		
PERIOD	-	
YEARS	:	20 th Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	÷	
Phone	•	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		

Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban	
		Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Story's	:	02 01
•	Spatial Organization Orientation	:	The School is oriented North – South and faces the North.
	Plan Allocation of Spaces	:	
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Compound wall, front yard, lattice work on railings.

10. Construction Technology

Structural System	:	Modern construction
Building Techniques	:	Corbelling system
Material of Construction	:	Brick, mortar, plaster

11. Condition Assessment

In

Good / Fair Good

Sign of Deterioration Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS