


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1175

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Radha Shyam Arukia ka haveli : :
LONGITUDE 75 [°] 4 [°] E	LATITUDE 28 ⁰ 13 ['] N
Address	Shri Mala ka Mohalla, Ward No.15
	: Village (village code) Post : Chirawa District: Jhunjhunu State : Rajasthan PIN: 333020
Approach	 The haveli situated in Shri Mala Ka Moholla at Chirawa. It is 30 km far from Jhunjhun and well connected by bus services.

3. Property Type



4. Property Use

		ABANDONED / IN USE : Abandoned
Present Past	:	Residential
5. Age (Source)		
PERIOD	:	
YEARS	:	20 th Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	<u>n</u>	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private	:	Radheshyam Arukia
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
• WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
✓ Architectural		
Archaeological		
Historical		
Religious		

Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban		
		Stand in Isolation Integral part of a Landscape / Street / Complex		
• Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)		
Number of Blocks Number of Storys	:	01 02		
Spatial Organization Orientation Plan Allocation of Spaces	:	The haveli is oriented North-South and faces North.		
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	:	Foliated arch. Carred wooden ponds fitted on port and tintel of doorway Courtyard, lattice railings, foliated arch porch.		
10. Construction Technology				
Structural System Building Techniques Material of Construction	: : :	Indo-Persian Arcuate and corbelling system. Brick, wood, mortar, plaster.		

11. Condition Assessment

In General

Good / Fair - good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS