



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1187

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Unknown Haveli  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 75° 4' E

LATITUDE 28° 13' N

#### Address

Ward no.-15, Chirawa

: **Village (village code)**

**Post** : Chirawa

**District**: Jhunjhunu

**State** : Rajasthan

**PIN**: 333026

#### Approach

: The Haveli is situated at Chirawa. It is 30km from Jhunjhunu. Well connected by private and govt. Bus service.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)  
**Haveli**

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is a single storey structure with a large foliated arch opening framing a post-Intel doorway. It has a prominent projecting terrace above the entrance area supported by brackets. The doorway is fitted with carved wooden panels. The structure has a central open courtyard.

#### 4. Property Use

---

**ABANDONED / IN USE :** In Use

**Present** : Residence  
**Past** : Residence

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 19<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context** : \* **Drawings** (Attach extra sheet if necessary)  
**Urban / Rural Setting** : Urban  
**Surroundings** : **Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
Number of Blocks : 01  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The Haveli is oriented East – West and faces the East.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Foliated arch, Post-Intel doorway, projecting terrace with brackets.  
Interiors : Courtyard  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate and corbelling system
- Material of Construction** : Bricks, Motar, Plaster.

### 11. Condition Assessment

---

<b>In General</b>	<b>Good / Fair</b>
	Good

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

#### **In Brief (Attach extra sheet if necessary):**

Discoloration of surface due to water seepage and peeling of plaster.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**