

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-133

	SECTION I : IDENTIFICATION			
1. Name				
Present Past Other Name (if any):	: Khetano ki Haveli (Unknown) :			
2. Location				
LONGITUDE 75° 4' E	LATITUDE 28 ⁰ 13 ['] N			
Address	Khetano ka Muhalla, Saith Manna Lal Khetan Marg			
	: Village (village code) Post : Jhunjhunu District: Jhunjhunu State : Rajasthan PIN: 333001			
Approach	: The Haveli is situated near Saith Mannalal Khaitan Marg.			

3. Property Type

	Buildings	<i>R</i>	eligious structures		Other Structures
	Palace	Те	mple		Wall
	Fort	Mc	sque		Gateway
	Citadel	Mir	nar		Pillar
	Govt. building	Ch	urch		Others (specify)
	Railway station	Mc	onastery		-
	Defence building	Stu	ıpa		
	Industrial building	То	mb, Mausoleum		
	Other public buildings				
\checkmark	Residential building				
	Engineering structure	Open struct	space and related ures	No wit	te: It is a magnificent haveli h beautiful facade having
	Engineering structure		ures	wit	0
		struct	•	wit arc	h beautiful façade having
	Bridge	struct Pu Pa	ures blic square	wit arc ser	h beautiful façade having aded designs and painting. The
	Bridge Tunnel	struct Pu Pa Gra	ures blic square rk or garden	wit arc ser sto arc	h beautiful façade having aded designs and painting. The ies of windows supported by ne brackets and made with aded frames having fluted
	Bridge Tunnel	struct Pu Pa Gra	u res blic square rk or garden aveyard olis, Well	wit arc ser sto arc pla	h beautiful façade having aded designs and painting. The ies of windows supported by ne brackets and made with aded frames having fluted sters make it highly impressive.
	Bridge Tunnel	struct Pu Pa Gra Ba	ures blic square rk or garden aveyard olis, Well nk	wit arc ser sto arc pla The	h beautiful façade having aded designs and painting. The ries of windows supported by ne brackets and made with aded frames having fluted sters make it highly impressive. e ceiling of this projected
	Bridge Tunnel	struct Pu Pa Gra Ba Ta	ures blic square rk or garden aveyard olis, Well nk	wit arc ser sto arc pla The wir	h beautiful façade having aded designs and painting. The ies of windows supported by ne brackets and made with aded frames having fluted sters make it highly impressive.

		ABANDONED / IN USE : In use
Present	:	Residence
Past	:	Residence
5. Age (Source)		
PERIOD	:	
YEARS		19 th Century A.D.
Precise date of Construction	÷	
Completion	÷	
Subsequent changes	÷	
Destruction / Demolition	:	
6. Ownership / Level of Protecti	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	•	Probably Saith Mannalal
Architect / Engineer	:	
Any other (specify)	÷	
9 Statement of Significance		
8. Statement of Significance		
✓ Architectural	Gr	and structure with fresco work.
Archaeological		
Historical		
Religious		

Religious Any other (specify)

SECTION II: DESCRIPTION

9.	Physical Description and De	cora	ative Features
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch)
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Haveli is oriented North – South and faces the South.
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	:	Arcaded designs Painting House hold items

10. Construction Technology

Structural System	:	Indo-Persian with predominant Rajasthani features
Building Techniques Material of Construction	:	Arcuate system Dressed masonry, Rubble masonry and lime plaster

11. Condition Assessment

In General	Good / Fair Fair	
Sign of Deterioration		

Serious Deterioration

 \checkmark

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening and peeling off plaster.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS