

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN - 1352

	SECTION I : IDENTIFICATION
1. Name	
Present Past Other Name (if any):	Banwari lal pawan kumar ki haveli
2. Location	
LONGITUDE 75° 4' E	LATITUDE 28 ⁰ 13 ['] N
Address	Near Nand Lal ki haveli, Ward no – 11
	: Village (village code) Post : Sultana District: Jhunjhunu State : Rajasthan PIN: 333028
Approach	 The haveli is situated near Nand lal haveli Sultana and 1 KM from bus stand Sultana. It is well connected by regular bus services via Chirawa to Jhunjhunu.
2 Property Type	

3. Property Type

	Buildings	Religious structures	Other Structures
	Palace	Temple	Wall
	Fort	Mosque	Gateway
	Citadel	Minar	Pillar
	Govt. building	Church	Others (specify)
	Railway station	Monastery	
	Defence building	Stupa	
	Industrial building	Tomb, Mausoleum	
	Other public buildings		
\checkmark	Residential building		
	Engineering structure	Open space and related structures	Note: It is an old dilapidated building having foliated arch
		structures	•
	<i>Engineering structure</i> Bridge Tunnel	<i>structures</i> Public square	building having foliated arch
	Bridge	structures	building having foliated arch opening. The door lintels are
	Bridge Tunnel	Structures Public square Park or garden	building having foliated arch opening. The door lintels are intricately carved. The stone brackets and exterior walls have faded paintings. The top floor of
	Bridge Tunnel	structures Public square Park or garden Graveyard	building having foliated arch opening. The door lintels are intricately carved. The stone brackets and exterior walls have faded paintings. The top floor of the building has foliated arches
	Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well	building having foliated arch opening. The door lintels are intricately carved. The stone brackets and exterior walls have faded paintings. The top floor of the building has foliated arches and projected chhajjas. The
	Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well Tank	building having foliated arch opening. The door lintels are intricately carved. The stone brackets and exterior walls have faded paintings. The top floor of the building has foliated arches

4. Property Use		
		ABANDONED / IN USE : In use
Present	:	Residence
Past	:	Residence
5. Age (Source)		
PERIOD	:	
YEARS	:	19 th Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protecti	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals		
In Building Construction		
Any other (specify)	:	
WITH PERSONS	-	
Patron	-	
Architect / Engineer	:	
Any other (specify)	:	
	•	
8. Statement of Significance		
✓ Architectural	Fre	esh dressed stone.
Archaeological		
Historical		
Delinious		

Religious
Any other (specify)

l

9.	Physical Description and De	cora	ative Features
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Story's	:	02 01
•	Spatial Organization Orientation Plan Allocation of Spaces	::	The haveli is oriented East – West and faces the East.
<u>AF</u> •	RCHITECTURAL STYLE Ornamentation Exteriors	:	It has foliated arch opening having beautiful Rajasthani fresco. Stone brackets are adorned with exquisite
Ar	Interiors Movable Collections ny Other (specify)	:	paintings.

10. Construction Technology

Structural System	:	Indo Persian
Building Techniques	:	Arcuate
Material of Construction	:	Brick & Stone

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Discoloration, blackening and peeling of plaster.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS