


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN - 1377

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any):	Sunil Kr Nand Lal Kumavad ki haveli
2. Location	
LONGITUDE 75 ⁰ 4 ['] E	LATITUDE 28 ⁰ 13 ['] N
Address	Ward no – 13, Khedi ka mohalla
Approach	 Village (village code) Post : Bagar District: Jhunjhunu State : Rajasthan PIN: 333023 The haveli is situated near Khedi ka mohalla and 1 KM
	from Bagar bus stand. It is well connected by regular bus and trains services.
2 Proporty Type	

3. Property Type



4. Property Use

		ABANDONED / IN USE : In use
Present	:	Residence
Past	:	Residence
5. Age (Source)		
PERIOD	:	
YEARS	:	19 th Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name Address	÷	
Phone	-	
FIIONE	•	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron Architect / Engineer	:	
Any other (specify)	-	
Any other (specify)	-	
8. Statement of Significance		

✓ Architectural
 Archaeological
 Historical
 Religious
 Any other (specify)

Dressed stone.

SECTION II: DESCRIPTION

 Context Urban / Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary) Urban
Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
• Quantification Area Dimension (L x B x H)	:	(m/om/fact/inch
Number of Blocks Number of Story's	:	(m / cm/ feet / inch 02
 Spatial Organization Orientation Plan Allocation of Spaces 	:	The haveli is oriented East – West and faces the West.
 ARCHITECTURAL STYLE Ornamentation Exteriors 	:	It can be approached through staircase. A foliated arcl opening at the entrance.
Interiors Movable Collections Any Other (specify)	:	The interior has decorative pattern on the wall.

10. Construction Technology

Structural System	:	Indo Persian
Building Techniques	:	Arcuate
Material of Construction	:	Brick & Stone

11. Condition Assessment

Good / Fair Good

Sign of Deterioration

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Dilapidated.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS