

## Documentation format for Archaeological / Heritage Sites / Monuments

### Serial No.: RJ/JJN-1398

#### **SECTION I: IDENTIFICATION** 1. Name Present 2 Sara of Mal Birla ka Haveli Past : Other Name (if any): : 2. Location **LONGITUDE** $75^{\circ}4^{\circ}E$ 28<sup>0</sup> 13<sup>'</sup> N LATITUDE Address Ward No.6, Pilani Village (village code) : Post : Pilani **District:** Jhunjhunu State : Rajasthan **PIN:** 333031 Approach : The haveli is situated near Birla Haveli Pilani and 500 m from bus stand, Pilani. It is 47 km from Jhunjhun and well connected by regular bus services.

## 3. Property Type

	Buildings		Religious structures		Other Structures
	Palace		Temple		Wall
	Fort		Mosque		Gateway
	Citadel		Minar		Pillar
	Govt. building		Church		Others (specify)
	Railway station		Monastery		
	Defence building		Stupa		
	Industrial building		Tomb, Mausoleum		
	Other public buildings				
./	Residential building				
v	Residential building				
•	Engineering structure	-	oen space and related ructures		te: It is an old haveli in a semi- ned state. It has foliated arch
• 	C C	-	ructures	ruir	
• 	Engineering structure	-	-	ruir ope	ned state. It has foliated arch
	Engineering structure Bridge	-	ructures Public square	ruir ope pai als	ned state. It has foliated arch ening having decorative intings. The vault of the arch is o adorned with fine Rajasthani
	Engineering structure Bridge Tunnel	-	r <b>uctures</b> Public square Park or garden	ruir ope pai als fres	ned state. It has foliated arch ening having decorative intings. The vault of the arch is o adorned with fine Rajasthani scos. There is a deity image on
	Engineering structure Bridge Tunnel	-	<b>ructures</b> Public square Park or garden Graveyard	ruir ope pai als fres the	ned state. It has foliated arch ening having decorative intings. The vault of the arch is o adorned with fine Rajasthani scos. There is a deity image on a lalat-bimba of the temple. The
	Engineering structure Bridge Tunnel	-	<b>ructures</b> Public square Park or garden Graveyard Baolis, Well	ruir ope pai als fres the doo	ned state. It has foliated arch ening having decorative intings. The vault of the arch is o adorned with fine Rajasthani scos. There is a deity image on

	ABANDONED / IN USE : In use
Dressent	Desidence
Present	: Residence
Past	: Residence
5. Age (Source)	
PERIOD	:
YEARS	19 <sup>th</sup> Century A.D.
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	an
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	: Sara of Birla
Any other (Please specify)	·
Name	
Address	
Phone	
7. Association	
WITH EVENTS	
In History	:
In Rituals	
In Building Construction	-
Any other (specify)	-
WITH PERSONS	-
Patron	
Architect / Engineer	
Any other (specify)	
Any other (specify)	•
8. Statement of Significance	
<ul> <li>✓ Architectural</li> </ul>	Dressed stone
Archaeological	
Historical	
Religious	

#### 9. Physical Description and Decorative Features \* **Drawings** (Attach extra sheet if necessary) Context **Urban / Rural Setting** Urban Surroundings Stand in Isolation Integral part of a Landscape / Street / Complex Quantification Area Dimension $(L \times B \times H)$ : (m / cm/ feet / inch) Number of Blocks 01 2 Number of Storys : 01 Spatial Organization Orientation The haveli is oriented East-West and faces the West. 1 Plan : Allocation of Spaces : **ARCHITECTURAL STYLE** Ornamentation It has small gate at the exterior having ornamental iron grills. Exteriors 2 The door is embellished with delicate, carving. The ceiling of the chhajjas and stone brackets have also beautiful Rajasthani frescos. Interiors 1 Movable Collections : **Any Other** (specify) 2 **10.** Construction Technology Indo-Persian Structural System : **Building Techniques** Arcuate : Material of Construction Brick and stone. : 11. Condition Assessment In General Good / Fair – Fair

**SECTION II: DESCRIPTION** 

Sign of Deterioration Serious Deterioration Danger of Disappearance

## In Brief (Attach extra sheet if necessary):

Blackening and peeling of plaster.

## 12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

# **SECTION III:** REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attack list as in some C in some of multiple shots months)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS