


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1405

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Durga Pd. Madelia ki haveli : :	
LONGITUDE 75 ⁰ 4 [°] E	LATITUDE 28 ⁰ 13 ['] N	
Address	Near Mandelia School, Ward No. 13	
Approach	 Village (village code) Post: Pilani District: Jhunjhunu State: Rajasthan PIN: 333031 The Haveli is situated near Mandelia School and 1500 m. from Bus stand Pilani. It is 47 k.m. from Jhunjhunu and well connected by regular bus service. 	

3. Property Type



4. Property Use

	ABANDONED / IN USE : Abandoned
Present	:
Past	: Residence
5. Age (Source)	
PERIOD	
YEARS	20 th Century A.D.
Precise date of Construction	- 20 Ochary A.D.
Completion	
Subsequent changes	
Destruction / Demolition	:
6. Ownership / Level of Protectio	n
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	
India / State Archaeology	•
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	: In History
In Rituals	:
In Building Construction	
Any other (specify)	:
WITH PERSONS	
Patron	
Architect / Engineer Any other (specify)	•
	•
8. Statement of Significance	
✓ Architectural	
Archaeological	
Historical	
Religious	
Any other (specify)	

9. Physical Description and Decorative Features * **Drawings** (Attach extra sheet if necessary) Context • **Urban / Rural Setting** Urban Surroundings Stand in Isolation Integral part of a Landscape / Street / Complex Quantification Area Dimension (L x B x H): (m / cm/ feet / inch) Number of Blocks 02 2 Number of Storys : 02 Spatial Organization Orientation The Haveli is oriented East- West & Faces the West. : Plan : Allocation of Spaces : **ARCHITECTURAL STYLE** Ornamentation Exteriors : It has multi-foliated arch with lattice work balcony supported by brackets. Interiors : It has decorative arches, brackets. The structure is of brick mortar. Movable Collections 2 **Any Other** (specify) 2

SECTION II: DESCRIPTION

10. Construction Technology

Structural System	:	Brick structure
Building Techniques	:	Joined by Brick & mortar
Material of Construction	:	Brick & mortar and Lime Mortar

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary)

Peeling of plaster and discoloration as well as it is encroached.

12. Threats to the Property

✓	Natural
	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS