

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1430

1. Name	SECTION I : IDENTIFICATIO	N
Present Past Other Name (if any):	: Sushil kumar singi hav : :	reli
2. Location		
LONGITUDE 75° 4' E	LATITUDE 28 ⁰ 13 ['] N	
Address	Near Sabu School (Ram L	ila Ground), Ward No. 8
Approach	Lila Ground) Pilani & 2	District: Jhunjhunu PIN: 333031 near Sabu School, Shyam (Ram 1500 M from Bus Stand Pilani. It unu & well connected by regular
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildings✓Residential building	Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic squarePark or gardenGraveyardBaolis, WellTankCave	Note: It is a double storied haveli. It is built on a raised platform which can be approached through staircase. It has multi foliated arch openings. The chhaja is supported by brackets. The interior of the brackets and chhaja has beautiful carving.

	ABANDONED / IN USE : In use
Present	: Residence
Past	: Residence
1 451	
5. Age (Source)	
PERIOD	:
YEARS	: 20 th Century A.D.
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
Architectural	
Archaeological	
Historical Religious	

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban	
	Carroundingo		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks	:	(m / cm/ feet / inch)
•	Number of Storys Spatial Organization Orientation Plan Allocation of Spaces	:	01 The haveli is oriented North - South & Faces the North.
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : : : : : : : : : : : : : : : : : : :	It is built on a raised platform.

10. Construction Technology

Structural System	:	Arcuate
Building Techniques	:	Brick & stone masonry
Material of Construction	:	Brick & stone.

11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary)

Discoloration.

12. Threats to the Property

✓	Natural
	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS