

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1499

SECTION I : IDENTIFICATION 1. Name Present Shivjee ka temple Past : Other Name (if any): 2 2. Location 28⁰ 13['] N LONGITUDE 75⁰ 4['] E LATITUDE Address Near Bodi ka well, Buhana Road, Ward No.19 : Village (village code) **Post :** singhana District: Jhunjhunu State : Rajasthan **PIN:** 333516 Approach The temple is situated near Bodi ka well/located : Buhana road Singhana and 1500 m from bus stand It is 68 km from Jhunjhun and well Singhana. connected by regular bus services. 3. Property Type **Religious structures Other Structures** Buildings Wall Palace Temple Fort Mosaue Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb. Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is an old temple adorned with pink colour. The temple has structures inverted lotus type of pinnacle. A Bridge Public square stone-image of Shivlinga flanked Tunnel Park or garden by other deities adorns the main-Other engineering structure Gravevard deity room of the temple. Baolis, Well Tank Cave

	ABANDONED / IN USE : In use
Dresset	Delizious
Present	: Religious
Past	: Religious
5. Age (Source)	
PERIOD	:
YEARS	: 19 th Century A.D.
Precise date of Construction	:
Completion	
Subsequent changes	
Destruction / Demolition	
6. Ownership / Level of Protection	an a
0. Ownership / Level of Frotection	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	
Any other (Please specify)	
Name	
Address	
Phone	
7. Association	
WITH EVENTS	
In History	<u>.</u>
In Rituals	
In Building Construction	
Any other (specify)	
WITH PERSONS	•
Patron	
Architect / Engineer	:
Any other (specify)	:
Any other (specify)	
8. Statement of Significance	
✓ Architectural	Brick and dressed stone.
Archaeological	
Historical	
Religious	

SECTION II: DESCRIPTION

9.	Physical Description and De	cor	ative Features
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban
	Curreariange		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / om / fact / inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The temple is oriented East-West and faces the West.
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	:	The temple has an inverted lotus type of pinnacle. It is painted with pink colour.
10	. Construction Technology		
	Structural System Building Techniques Material of Construction	:	Indo-Persian Brick and Stone masonry Brick and stone.
11	. Condition Assessment		
	In General Go	ood	/ Fair – Good
	Sign of Deterioration Serious Deterioration Danger of Disappearance		

In Brief (Attach extra sheet if necessary):

Discolouration and vegetational growth.

12. Threats to the Property

✓ Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attack list as in some C in some of multiple shots months)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS