



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1616

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Mahavir Pd Narnoi Ki Haveli  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 75° 4' E

**LATITUDE** 28° 13' N

#### **Address**

Near Post Office, Ward No.-12

: **Village (village code)**

**Post** : Udaipurwati

**District:** Jhunjhunu

**State** : Rajasthan

**PIN:** 333307

#### **Approach**

: The Haveli is situated near Post Office. And 500m from Bus Stand Udaipurwati. It is 52km from Jhunjhunu and well connected by bus services.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** This two floored haveli complex has a high nice foliated arched gateway with a wooden door. The arch is plain & simple painted with white lime.

#### 4. Property Use

---

ABANDONED / IN USE : IN USE

**Present** : Residence  
**Past** : Residence

#### 5. Age (Source)

---

**PERIOD** : 19<sup>th</sup> century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

SINGLE /MULTIPLE :

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 02  
Number of Storys : 02
  
- **Spatial Organization**  
Orientation : The Haveli is oriented North-south and faces the north.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : The paintings essentially have procession royal animals & floral patterns in Red, Blue, Green & yellow.  
  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate
- Material of Construction** : Stone, Rubble masonry, Lime etc.

### 11. Condition Assessment

---

In General	Good / Fair	Good
------------	-------------	------

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

#### **In Brief (Attach extra sheet if necessary):**

Major painted portions are missing. The present paintings are fading or crush ling off.

## 12. Threats to the Property

---

- |   |                 |
|---|-----------------|
| ✓ | Natural         |
| ✓ | Negligence      |
| ✓ | Vandalism       |
| ✓ | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**