



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1624

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Kuman Chand Jee Ki Haveli  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 75° 4' E

**LATITUDE** 28° 13' N

#### Address

Sabaji Mandi, Ward No.-15

: **Village (village code)**

**Post** : Udaipurwati

**District:** Jhunjhunu

**State** : Rajasthan

**PIN:** 333307

#### Approach

: The haveli is situated Sabaji Mandi. And 1km from Bus Stand Udaipurwati. It is 52km from Jhunjhunu and it is well connected by bus services of govt. & non-govt services.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** The plain high rise facade of this complex has some nominates of wall frescos depicting floral patterns, royal processions, court scansion Especially the spandrel has medallion like paintings.

#### 4. Property Use

---

ABANDONED / IN USE : IN USE

**Present** : Residence  
**Past** : Residence

#### 5. Age (Source)

---

**PERIOD** : 16<sup>th</sup> century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

SINGLE /MULTIPLE :

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context** : \* **Drawings** (Attach extra sheet if necessary)  
**Urban / Rural Setting** : Urban  
**Surroundings** : **Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
Number of Blocks : 01  
Number of Storys : 04
  
- **Spatial Organization**  
Orientation : The haveli is oriented east-west and faces the east.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Some of the wooden doors inside has screened transoms.  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate
- Material of Construction** : Stone, rubble masonry, bricks etc.

### 11. Condition Assessment

---

In General	Good / Fair	Good
------------	-------------	------

- |                                     |                         |
|-------------------------------------|-------------------------|
| <input type="checkbox"/>            | Sign of Deterioration   |
| <input checked="" type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/>            | Danger of Disappearance |

#### **In Brief (Attach extra sheet if necessary):**

The painted portions are fading & climbing Inside the plaster has disappeared soot dirt & dust.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input checked="" type="checkbox"/> | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

##### **NAME**

##### **NAME**

#### **18. Reviewers**

##### **NAME**

##### **NAME**

##### **COMMENTS**

##### **COMMENTS**