

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-163

SECTION I : IDENTIFICATION 1. Name		
Present Past Other Name (if any): 2. Location	: Motiram ji Swami ka H : Wakilo ka Haveli	Haveli
LONGITUDE 75° 4' E	LATITUDE 28° 13' N	
Address	Akha Garh, Khetan Muha : Village (village code Post: Jhunjhunu State: Rajasthan	,
Approach	: The Haveli is situated	near Akha Garh
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar ✓ Others (specify) Haveli
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: This place is a house. Its main gate is made of iron. At the gate pointed and foliated arches can be seen and with it paintings can also be seen. Inside there is a fabulous pattern of various kinds of paintings. In the interior pointed and foliated arches are used. Chajja is also present in tilted style.

4. Property Use		
	ABANDONED / IN USE :	In use
Present Past	Residence Residence	
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	19 th Century A.D.	
6. Ownership / Level of Protection		
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	SINGLE /MULTIPLE : Motiramji Akha Garh Wakilo Haveli, Jhui 9694953049	njhunu, W-37
7. Association		
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify)		
8. Statement of Significance		
✓ Architectural Archaeological Historical Religious Any other (specify)	eat use of arches and paint work i	n house with windows.

SECTION II: DESCRIPTION

9. Physical Description and	Decorative Features	
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) Urban	
Carroundings	Stand in Isolation Integral part of a Landscape / Street / Complex	
Quantification Area Dimension (L x B x F)	l) : (m / cm/ feet / inch)	
Number of Blocks Number of Storys	: 02 : 02	
 Spatial Organization Orientation Plan Allocation of Spaces 	: The Haveli is oriented North-South and facing the North : :	
• Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	A gate with foliated and pointed archesArch pattern and paintings on walls and ceiling..	
10. Construction Technology	1	
Structural System Building Techniques Material of Construction	: A house (Modern Construction): A multiple arch pattern: Brick and plaster	
11. Condition Assessment		
In General	Good / Fair Good	
Sign of Deterioration Serious Deterioration Danger of Disappearance		
In Brief (Attach extra sheet i	necessary):	
Peeling off plaster and discolo	ration painted layers.	

12. Threats to the Property	
	✓ Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS