

**INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS** 

Janpath, New Delhi -110 001, www.ignca.gov.in

# Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: RJ/JJN-1682

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any):	Shivjee Ka Temple	
2. Location		
LONGITUDE 75° 4' E	LATITUDE 28 <sup>0</sup> 13 <sup>'</sup> N	
Address	Near Ramlila Maidan Ward No22	
	: Village (village code) Guda Post : Guda District: Jhunjhunu State : Rajasthan PIN: 333022	
Approach	: The temple is situated Guda located near Ramlila Maidan Guda. 1km from Bus Stand Guda. It is 33km from Jhunjhunu & well connected by bus services.	
3. Property Type		
Buildings	Religious structures Other Structures	

 bullalliys		Religious structures		Other Structures
Palace	$\checkmark$	Temple		Wall
Fort		Mosque		Gateway
Citadel		Minar		Pillar
Govt. building		Church		Others (specify)
Railway station		Monastery		_
Defence building		Stupa		
Industrial building		Tomb, Mausoleum		
Other public buildings				
Residential building				
Residential building				
Engineering structure	•	en space and related ructures		<b>te:</b> Within a high rise boundary
5	•	•	wa	<b>te:</b> Within a high rise boundary Il the temple complex has a ated arched gateway. Inside
Engineering structure	•	ructures	wa foli the	Il the temple complex has a ated arched gateway. Inside complex is an open courtyard
Engineering structure Bridge	•	r <b>uctures</b> Public square	wa foli the	Il the temple complex has a ated arched gateway. Inside
Engineering structure Bridge Tunnel	•	r <b>uctures</b> Public square Park or garden	wa foli the with sar	Il the temple complex has a ated arched gateway. Inside complex is an open courtyard h shrines sllavamd. The main nctum has a 'shivling' with his
Engineering structure Bridge Tunnel	•	r <b>uctures</b> Public square Park or garden Graveyard	wa foli the with sar	Il the temple complex has a ated arched gateway. Inside complex is an open courtyard h shrines sllavamd. The main
Engineering structure Bridge Tunnel	•	<b>Tuctures</b> Public square Park or garden Graveyard Baolis, Well	wa foli the with sar	Il the temple complex has a ated arched gateway. Inside complex is an open courtyard h shrines sllavamd. The main nctum has a 'shivling' with his

#### 4. Property Use ABANDONED / IN USE : IN USE Present Religious : Religious Past : 5. Age (Source) 20<sup>th</sup> century A.D. PERIOD 2 YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address : Phone ÷ 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Archaeological Historical Religious

Any other (specify)

# SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 02 01
•	<b>Spatial Organization</b> Orientation Plan Allocation of Spaces	:	The temple is oriented east-west and faces the east.
•	<b>RCHITECTURAL STYLE</b> <b>Ornamentation</b> Exteriors Interiors Movable Collections <b>by Other</b> (specify)	: : : : : : : : : : : : : : : : : : : :	The gate is plain. Floral & religious scenes are painted.

### **10. Construction Technology**

Structural System Building Techniques Material of Construction	:	Indo-Persian Arcuate Stone, rubble, lime plaster etc.
Material of Construction	:	Stone, rubble, lime plaster etc.

#### 11. Condition Assessment

In General	
------------	--

Good / Fair

Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

## In Brief (Attach extra sheet if necessary):

Lacks maintenance, blackening, peeling of plaster.

## 12. Threats to the Property

$\checkmark$	Na
$\checkmark$	Ne
$\checkmark$	Va
$\checkmark$	Ur

Natural Negligence Vandalism Urban Pressures

# SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS