



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-169

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Sita Ram Banka Bhawan  
Past :  
Other Name (if any): :

#### 2. Location

LONGITUDE 75° 4' E

LATITUDE 28° 13' N

#### Address

Shri Malo Ka Mohalla, W-36, Jhunjhunu

: **Village (village code)**

**Post** : Jhunjhunu

**District**: Jhunjhunu

**State** : Rajasthan

**PIN**: 333001

#### Approach

: The Building is located near Shri Malo ka Mohalla.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)  
**Bhawan**

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is grand structure with arcaded verandah at the front. The arches are circular and are based on fluted columns. The arch of the main entrance is foliated and has perforated and tendril patterns that cover its spandrels.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Residence  
**Past** : Residence

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 19<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :  
**Private** :  
**Any other (Please specify)** :  
**Name** : Sita Ram Banka  
**Address** : Shri Malo ki Muhalla, W-36, Jhunjhunu  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |  |
|-------------------------------------|---------------------|--|
| <input checked="" type="checkbox"/> | Architectural       | Double storeyed structure with arcaded verandah. |
| <input type="checkbox"/>            | Archaeological      |  |
| <input type="checkbox"/>            | Historical          |  |
| <input type="checkbox"/>            | Religious           |  |
| <input type="checkbox"/>            | Any other (specify) |  |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 01  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The Bhawan is oriented North-South and facing the South  
  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Arcaded verandah  
Interiors : Rooms  
Movable Collections : House hold items  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Modern Construction
- Building Techniques** : Arcuate system, English bond method
- Material of Construction** : Bricks, stone and plaster

### 11. Condition Assessment

---

In General	Good / Fair
	Good

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

**In Brief (Attach extra sheet if necessary):**

Plaster is blackening and peeling off

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

##### **NAME**

##### **NAME**

#### **18. Reviewers**

##### **NAME**

##### **NAME**

##### **COMMENTS**

##### **COMMENTS**