


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1691

SECTION I : IDENTIFICATION		
1. Name		
Present Past Other Name (if any):	: Purshutam lal pansari ka haveli :	
2. Location		
LONGITUDE 75° 4' E	LATITUDE 28 ⁰ 13 ['] N	
Address	Pansari ka mohalla Ward No21	
	: Village (village code) Guda Post : Guda District: Jhunjhunu State : Rajasthan PIN: 333022	
Approach	The haveli is situated Guda located pansari mohalla. And 1km from Bus Stand Guda. It is 33km from Jhunjhunu & well connected by bus services.	
3. Property Type		
5		



4. Property Use

		ABANDONED / IN USE : IN USE		
Present	:	Residence		
Past	:	Residence		
5. Age (Source)				
PERIOD	:	19 th century A.D.		
YEARS	:			
Precise date of Construction	:			
Completion	:			
Subsequent changes	:			
Destruction / Demolition	:			
6. Ownership / Level of Protection				
		SINGLE /MULTIPLE :		
Public : Archaeological Survey of	:			
India / State Archaeology				
Department / Any Other (Please				
specify)				
Private	:			
Any other (Please specify)	:			
Name	:			
Address	:			
Phone	:			
7. Association				
WITH EVENTS				
In History	:			
In Rituals	:			
In Building Construction	:			
Any other (specify)	:			
WITH PERSONS				
Patron	:			
Architect / Engineer	:			
Any other (specify)	:			
8. Statement of Significance				
Architectural				
Archaeological				

Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and De	ecorative Features				
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) Urban				
Surroundings	Stand in Isolation Integral part of a Landscape / Street / Complex				
• Quantification Area Dimension (L x B x H)	: (m / cm/ feet / inch)				
Number of Blocks Number of Storys	: 02 01				
 Spatial Organization Orientation Plan Allocation of Spaces 	The haveli is oriented North-south and faces the north.				
ARCHITECTURAL STYLE Ornamentation Exteriors Interiors	 The carved arches on the facade are also painted with geometrical patterns. 				
Movable Collections Any Other (specify) 10. Construction Technology	· :				
Structural System Building Techniques Material of Construction	 Indo-Persian Arcuate Stone, rubble masonry, bricks cement etc. 				
11. Condition Assessment					
In General G	Good / Fair Good				
 ✓ Sign of Deterioration Serious Deterioration Danger of Disappearance 					
In Brief (Attach extra sheet if r	In Brief (Attach extra sheet if necessary):				
-Decays of plaster & exterior wal -Blackening, fading etc. -Unplanned exterior.					

12. Threats to the Property

\checkmark	Na
\checkmark	Ne
\checkmark	Va
\checkmark	Ur

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	· · · · · · · · · · · · · · · · · · ·
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS