



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-170

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Lakshmi Narain Banka Bhawan  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 75° 4' E

**LATITUDE** 28° 13' N

#### **Address**

Shri Malo Ka Mohalla Chain, Dada Bari, W-36, Jhunjhunu

: **Village (village code)**

**Post** : Jhunjhunu

**District**: Jhunjhunu

**State** : Rajasthan

**PIN**: 333001

#### **Approach**

: The Haveli is located in Shri Malo ka Mohalla.

#### 3. Property Type

##### **Buildings**

- |                                     |                        |
|-------------------------------------|------------------------|
| <input type="checkbox"/>            | Palace                 |
| <input type="checkbox"/>            | Fort                   |
| <input type="checkbox"/>            | Citadel                |
| <input type="checkbox"/>            | Govt. building         |
| <input type="checkbox"/>            | Railway station        |
| <input type="checkbox"/>            | Defence building       |
| <input type="checkbox"/>            | Industrial building    |
| <input type="checkbox"/>            | Other public buildings |
| <input checked="" type="checkbox"/> | Residential building   |

##### **Religious structures**

- |                          |                 |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple          |
| <input type="checkbox"/> | Mosque          |
| <input type="checkbox"/> | Minar           |
| <input type="checkbox"/> | Church          |
| <input type="checkbox"/> | Monastery       |
| <input type="checkbox"/> | Stupa           |
| <input type="checkbox"/> | Tomb, Mausoleum |

##### **Other Structures**

- |                                     |                  |
|-------------------------------------|------------------|
| <input type="checkbox"/>            | Wall             |
| <input type="checkbox"/>            | Gateway          |
| <input type="checkbox"/>            | Pillar           |
| <input checked="" type="checkbox"/> | Others (specify) |
- Bhawan**

##### **Engineering structure**

- |                          |                             |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge                      |
| <input type="checkbox"/> | Tunnel                      |
| <input type="checkbox"/> | Other engineering structure |

##### **Open space and related structures**

- |                          |                |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square  |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard      |
| <input type="checkbox"/> | Baolis, Well   |
| <input type="checkbox"/> | Tank           |
| <input type="checkbox"/> | Cave           |

**Note:** It is an old dilapidated haveli with a foliated arch entrance. The door frame is embellished.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Residence  
**Past** : Residence

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 19<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :  
**Private** :  
**Any other (Please specify)** :  
**Name** : Lakshmi Narain  
**Address** : Chain Dada Bari, Muhalla Malo ka, W-36, Jhunjhunu  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |   |
|-------------------------------------|---------------------|---|
| <input checked="" type="checkbox"/> | Architectural       | Foliated arch and embellished door frame. |
| <input type="checkbox"/>            | Archaeological      |   |
| <input type="checkbox"/>            | Historical          |   |
| <input type="checkbox"/>            | Religious           |   |
| <input type="checkbox"/>            | Any other (specify) |   |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context** : \* **Drawings** (Attach extra sheet if necessary)  
**Urban / Rural Setting** : Urban  
**Surroundings** : **Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
Number of Blocks : 01  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The Bhawan is oriented North-South and facing the South  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Engrailed arch opening  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate system
- Material of Construction** : Rubble Masonry and plaster

### 11. Condition Assessment

---

<b>In General</b>	<b>Good / Fair</b>
	Good

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

#### **In Brief (Attach extra sheet if necessary):**

Core materials are exposed due to peeling of plaster.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

**NAME**

**NAME**

#### **18. Reviewers**

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**