

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1711

SECTION I: IDENTIFICATION 1. Name			
Present Past Other Name (if any):	: Modi Bhawan :		
2. Location			
LONGITUDE 75° 4' E	LATITUDE 28 ⁰ 13 ¹ N		
Address	Telia Mohalla, Ward No-28		
Approach 3. Property Type	Mohalla. And 1Km fron	Guda District: Jhunjhunu PIN: 333022 ated in Guda-Located Telia n Bus stand Guda. It is 33Km Connected by the bus services C.	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)	
Engineering structure Bridge Tunnel Other engineering structure	<u>str</u> uctures	Note: Raised on a plinth this structure has thick lofty walls with a round arch at the gateway.	

4. Property Use		
		ABANDONED / IN USE: In Use
Present	:	Locked
Past	:	Residence
5. Age (Source)		
PERIOD	:	20 th Century AD
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on_	
		SINGLE /MULTIPLE :
Public: Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	•	
7. Association		
 WITH EVENTS 		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	•	
Any other (specify)	•	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9. Physical Description and	Decora	ative Features
 Context Urban / Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary) Urban
our ourum go		Stand in Isolation Integral part of a Landscape / Street / Complex
Quantification Area Dimension (L x B x I	H) :	(m / cm/ feet / inch)
Number of Blocks Number of Storys	:	01 01
 Spatial Organization Orientation 	:	The Bhawan is oriented North-South and faces-The South
Plan Allocation of Spaces	:	South
• Ornamentation		
Exteriors Interiors Movable Collections Any Other (specify)	: : : : : : : : : : : : : : : : : : : :	Plain wood door painted in blue.
10. Construction Technolog	у	
Structural System Building Techniques Material of Construction 11. Condition Assessment	; ; ;	Indo Persian Arcuate Stone, Nibble masonary
In General	Good Good	/ Fair
Sign of Deterioration Serious Deterioration Danger of Disappearance	e	
In Brief (Attach extra sheet i	f nece	ssary):
In very poor state. Exposed ni	bble bla	acking.

12. Threats to the Property

✓ Natural✓ Negligence✓ Vandalism✓ Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS