

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

# Documentation format for Archaeological / Heritage Sites / Monuments

### Serial No.: RJ/JJN-174

| SECTION I : IDENTIFICATION 1. Name  |  |  |  |  |
|---|--|--|--|--|
| Present<br>Past<br>Other Name (if any):   | : Kalyan Bhawan<br>:   |  |  |  |
| 2. Location   |  |  |  |  |
| LONGITUDE 75° 4' E  | <b>LATITUDE</b> 28 <sup>0</sup> 13 <sup>'</sup> N  |  |  |  |
| Address   | Dada Bari, Shri Malo ka Mohalla, Jhunjhunu W-36  |  |  |  |
| Approach  | <ul> <li>Village (village code)<br/>Post : Jhunjhunu District: Jhunjhunu<br/>State : Rajasthan PIN: 333001</li> <li>The Building is situated in Shri Malo ka Muhalla near<br/>Dada Bari</li> </ul>   |  |  |  |
| 3. Property Type  |  |  |  |  |
| Buildings         Palace         Fort         Citadel         Govt. building         Railway station         Defence building         Industrial building         Other public buildings         Residential building | Religious structures       Other Structures         Temple       Wall         Mosque       Gateway         Minar       Pillar         Church       ✓         Monastery       Bhawan         Stupa       Tomb, Mausoleum  |  |  |  |
| Engineering structure Bridge Tunnel Other engineering structure   | Open space and related<br>structuresNote:It is made on raised<br>platform. The frontal verandah<br>has circular arches based on<br>cylindrical columns.Park or garden<br>Baolis, Well<br>Tank<br>CaveNote:It is made on raised<br>platform. The frontal verandah<br>has circular arches based on<br>cylindrical columns. |  |  |  |

### 4. Property Use

|  | ABANDONED / IN USE :                               |
|--|--|
| Present<br>Past  | : Residential                                      |
| 5. Age (Source)  |  |
| PERIOD<br>YEARS<br>Precise date of Construction<br>Completion<br>Subsequent changes<br>Destruction / Demolition  | 19 <sup>th</sup> Century A.D.                      |
| 6. Ownership / Level of Protection   | on   |
|  | SINGLE /MULTIPLE :                                 |
| Public : Archaeological Survey of<br>India / State Archaeology<br>Department / Any Other (Please<br>specify)<br>Private  | :  |
| Any other (Please specify)   | :  |
| Name<br>Address  | : Kalyan ji<br>: Chain, Dada Bari, Jhunjhunu, W-36 |
| Phone  | : Chain, Daua Ban, Shunjhunu, W-So                 |
| 7. Association   |  |
| <ul> <li>WITH EVENTS<br/>In History<br/>In Rituals<br/>In Building Construction<br/>Any other (specify)</li> <li>WITH PERSONS<br/>Patron<br/>Architect / Engineer<br/>Any other (specify)</li> </ul> |  |
| 8. Statement of Significance   |  |
| <ul> <li>✓ Architectural</li> <li>Archaeological</li> <li>Historical</li> <li>Religious</li> <li>Any other (specify)</li> </ul>  | Large Haveli                                       |

### **SECTION II: DESCRIPTION**

| <ul> <li>Context<br/>Urban / Rural Setting<br/>Surroundings</li> </ul> |  |   | * <b>Drawings</b> (Attach extra sheet if necessary)<br>Urban          |  |  |
|--|--|---|---|--|--|
|  | Sunounungs   |   | Stand in Isolation<br>Integral part of a Landscape / Street / Complex |  |  |
| •  | <b>Quantification</b><br>Area Dimension ( L x B x H)   | : | (m. / om / foot / in ch)  |  |  |
|  | Number of Blocks<br>Number of Storys   | : | (m / cm/ feet / inch)<br>02<br>02                                     |  |  |
| •  | Spatial Organization<br>Orientation  | : | The Bhawan is oriented North-South and facing the East-North          |  |  |
|  | Plan<br>Allocation of Spaces   | : |   |  |  |
| <u>A</u> [<br>•  | <b>RCHITECTURAL STYLE</b><br><b>Ornamentation</b><br>Exteriors<br>Interiors<br>Movable Collections | : | Circular Arches<br>Rooms<br>House hold items                          |  |  |
| A  | ny Other (specify)   | : |   |  |  |

| Structural System          | : | Modern construction      |
|----------------------------|---|--------------------------|
| <b>Building Techniques</b> | : | English bond method      |
| Material of Construction   | : | Brick, stone and plaster |

#### **11. Condition Assessment**

Good / Fair Good

Sign of Deterioration Serious Deterioration

Serious Deterioration

Danger of Disappearance

### In Brief (Attach extra sheet if necessary):

Plaster is blackening and peeling off

# 12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

# SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

| 14. Photographs         |   |
|-------------------------|---|
|                         | (attach list as in page 6, in case of multiple photographs) |
| Photo Reference         |   |
| CAPTION                 |   |
| 15. Audio / Video       |   |
|                         | (related to rituals / performance / festivals etc.)         |
| Reference               |   |
| DESCRIPTION             |   |
| 16. Maps/Plans/Drawings |   |
|                         |   |
|                         |   |
| 17. Listers             |   |
| NAME                    | NAME  |
| 18. Reviewers           |   |
| NAME                    | NAME  |
| COMMENTS                | COMMENTS  |